

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013854/T1TF3E2
Date: 06/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993892
Claimant Vehicle No : SLZ9724G **Insured Vehicle No :** SMU3932B
Date of Loss: 11/12/2020 Nature of Claim: TP Claim No: 6969870718SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ9724G**
Make & Model: TOYOTA PRIUS HYBRID, 1.8 S CVT (A) Engine No: 2ZR8280103
Reg. Date: 24/05/2018 (Man. Year: 2017) Chassis No: ZVW506104251
Colour: White Odometer: 166232 km
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/12/2020
Date Inspected: 15/12/2020 Inspected At: Apex Motoring
25 Kaki Bukit Road 4, #01-55 Synergy @ KB
Singapore 417800
Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Bent	0.00 F	*- F
2	1		*FRT RH DOOR LOCK	* Check	0.00 F	*- F
3	1		*FRT RH DOOR INNER TRIMBOARD	* Check	0.00 F	*- F
4	1		*FRT RH DOOR WEATHERSTRIP	Necessary	0.00 F	*- F
5	1		*FRT RH DOOR BLACK STICKER	Necessary	0.00 F	*- F
6	1		*REAR RH DOOR	Bent	0.00 F	*- F
7	1		*REAR RH DOOR BLACK STICKER	Necessary	0.00 F	*- F
8	1		*REAR RH DOOR WEATHERSTRIP	Necessary	0.00 F	*- F
9	1		*REAR RH DOOR INNER TRIMBOARD	* Check	0.00 F	*- F
10	1		*REAR RH DOOR WINDOW LIFTER MECHANISM	* Check	0.00 F	*- F
11	1		*REAR RH FENDER	Repair	0.00 F	*- F
12	1		*RH SIDE SILL GARNISH	Cut	0.00 F	*- F
13	1		*REAR RH DOOR HINGE	* Check	0.00 F	*- F
14	1		*RH CENTRE PILLAR	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >