

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20013856/UGS3Q2

Date: 16/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SGJ1214H	Insured Vehicle No :	SH6441D
Date of Loss: 11/12/2020	Nature of Claim:	TP Claim No: MCT20120300

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGJ1214H	Engine No:	1NZX443806
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY4204192606
Reg. Date:	29/06/2006 (Man. Year: 2006)	Odometer:	369836 km
Colour:	Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R14	Rear Tyre Size:	175/65 R14
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,082.44	0.00	2,082.44	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	900.00	770.00	46.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,752.44	900.00	2,852.44	76.02
+ GST 7.00/7.00% (S\$)	262.67	63.00	199.67	76.02
Nett Amount (S\$)	4,015.11	963.00	3,052.11	76.02
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
		1,143.00		

INSPECTION

Date of Assignment:	03/02/2021	
Date Inspected:	03/02/2021	Inspected At:
		Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012 Singapore 489977
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2021)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGJ1214H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	179.90 FL	*- FL
2	1		*FRONT BUMPER	Repair	278.90 FL	*- FL
3	1		*FRONT BUMPER RETAINER LH	Not Necessary	20.80 FL	*- FL
4	1		*HEADLAMP LH	Not Necessary	249.96 FL	*- FL
5	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	67.85 FL	*- FL
6	1		*FRONT FENDER SIGNAL LAMP LH	Not Necessary	78.95 FL	*- FL
7	1		*SET ENGINE MOUNTING	Not Necessary	486.90 FL	*- FL
8	1		*FRONT WHEEL RIM LH (CUT)	Not Consistent With The Impact	680.00 FS	*- FS
9	1		*FRONT TYRE LH	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,423.26	0.00
- List Item Discount on L Items 25.00/25.00% (\$)	340.82	0.00
Total Parts (\$)	2,082.44	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	550.00
3	ANTI-RUST COATING	New	150.00	30.00
4	WIRING	New	40.00	20.00
5	TWO WHEEL ALIGNMENT	New	80.00	0.00
			Gross Labour Cost (\$)	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >