

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013857/EQD3E2
Date: 05/02/2021

REFERENCE

Insured/Claimant: KO TUCK CHONG WILLY Policy No: 2100477891
Date of Loss: 14/12/2020 Nature of Claim: OD Claim No: 6132702973SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF145S**
Make & Model: MITSUBISHI ASX, 2.0 (A) Engine No: 4B11RS3216
Reg. Date: 11/08/2016 (Man. Year: 2016) Chassis No: JMFXTGA2WFZC19242
Colour: Silver Odometer: 41642 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$58,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,462.02	5,112.01	2,350.01	31.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,480.00	3,540.00	940.00	20.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,942.02	8,652.01	3,290.01	27.55
+ GST 7.00/7.00% (S\$)	835.94	605.64	230.30	27.55
Nett Amount (S\$)	12,777.96	9,257.65	3,520.31	27.55

INSPECTION

Date of Assignment: 15/12/2020

Date Inspected: 15/12/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*FACE, FR BUMPER	Broken	1,036.00 FL	*1,036.00 FL
3	1		*REINFORCEMENT, FR BUMPER	Bent	53.00 FL	*53.00 FL
4	1		*COVER, HEADLAMP SUPT PANEL	Not Necessary	135.00 FL	*- FL
5	1		*COVER, FR BUMPER	Not Necessary	66.00 FL	*- FL
6	1		*FENDER, FR RH	Dented	510.00 FL	*510.00 FL
7	1		*SHIELD, FR WHEELHOUSE, RH	Torn	146.00 FL	*146.00 FL
8	1		*PANEL ASSY, FR DOOR, RH	Dented	882.00 FL	*882.00 FL
9	1		*W/STRIP, F/DR OPENG, LWR LH	Not Necessary	47.00 FL	*- FL
10	1		*RUNCHANNEL, F/DR WDO GLA, RH	Not Necessary	143.00 FL	*- FL
11	1		*W/STRIP, FR DR OPNG, OTR RH	Not Necessary	168.00 FL	*- FL
12	1		*MLDG, F/DR WDO BELT LINE, RH	Bent	130.00 FL	*130.00 FL
13	1		*GLASS, FR DOOR WINDOW, RH	Cut	189.00 FL	*189.00 FL
14	1		*TAPE, FR DOOR SASH	Necessary	36.00 FL	*36.00 FL
15	1		*AIR DAM, SIDE, RH	Not Necessary	541.00 FL	*- FL
16	1		*GARNISH, FR FENDER, RH	Missing	89.00 FL	*89.00 FL
17	1		*MIRROR ASSY, DOOR, RH	Missing	472.00 FL	*472.00 FL
18	1		*COVER, DOOR MIRROR, OTR RH	Missing	138.00 FL	*138.00 FL
19	1		*MOULDING, FR WHEEL ARCH, RH	Broken	132.00 FL	*132.00 FL
20	1		*WHEEL, SPARE TIRE DISC	Cut	1,102.00 FL	*1,102.00 FL
21	1		*STRUT, FR SUSP, RH	Not Necessary	484.00 FL	*- FL
22	1		*LINK, FR SUSP STABILIZER	Not Necessary	137.00 FL	*- FL
23	1		*PAD, FR SUSP SPRING, LWR	Not Necessary	15.00 FL	*- FL
24	1		*BEARING, FR SUSP STRUT	Not Necessary	27.00 FL	*- FL
25	1		*DAMPER, FR SUSP STRUT	Not Necessary	39.00 FL	*- FL
26	1		*GEAR & LINK ASSY, STEERING	Not Necessary	1,211.00 FL	*- FL
27	1		*HEADLAMP ASSY, RH (Supplementary)	Broken	824.00 FL	*824.00 FL
28	1		*HEADLAMP ASSY, LH (Supplementary)	Broken	824.00 FL	*824.00 FL
29	10		*CLIPS (Supplementary)	Necessary	20.00 FL	*20.00 FL
30	10		*CLIPS (Supplementary)	Necessary	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,676.00	6,633.00
- List Item Discount on L Items 23.00/23.00% (\$)	2,213.98	1,520.99
Total Parts (\$)	7,462.02	5,112.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, FRT RH FENDER, FRT RH DOOR & AFFECTED AREA	New	1,800.00	1,350.00
2	PAINT WORK ON FRT BUMPER, FRT RH FENDER & FRT RH DOOR	New	1,050.00	1,050.00
3	TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL	New	120.00	120.00
4	PERFORM RUST PREVENTION	New	40.00	0.00
5	REPLACE FRONT UNDERCARRIAGE	New	450.00	0.00
6	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
7	TO TRANSFER FRT RH RIM INCLUDING BALANCING	New	30.00	30.00
8	TO SUPPLY FRT RH TYRE	New	480.00	480.00
9	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
11	TO APPLY ZERTONA COATING ON AFFECTED AREA	New	240.00	240.00
			Gross Labour Cost (\$\$)	3,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >