

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20013859/UTF3E2
Date: 11/01/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : GBK982J **Insured Vehicle No :** GZ5548J
Date of Loss: 04/12/2020 Nature of Claim: TP Claim No: CDMCG20001831

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK982J**
Make & Model: CITROEN BERLINGO, 1.5 D BLUEHDI EAT8 (M) Engine No: 10Q4DR0003332
Reg. Date: 27/12/2019 (Man. Year: 2019) Chassis No: VR7EFYHZRKJ732865
Colour: Grey Odometer: 15988 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,301.47	2,189.39	4,112.08	65.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,725.00	830.00	895.00	51.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,026.47	3,019.39	5,007.08	62.38
+ GST 7.00/7.00% (S\$)	561.85	211.36	350.49	62.38
Nett Amount (S\$)	8,588.32	3,230.75	5,357.57	62.38

INSPECTION

Date of Assignment: 15/12/2020
Date Inspected: 16/12/2020 Inspected At: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)
Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT
Singapore 417800
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$3,019.38

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Jan 2021)	
Parts:	N/A	CITROEN BERLINGO 1.5 D BLUEHDI EAT8 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK982J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Badly Dented	2,003.22 FL	*1,815.00 FL
2	1		*FRONT LH DOOR HINGE TOP	Not Necessary	233.33 FL	*- FL
3	1		*FRONT LH DOOR GLASS OUTER MOULDING	Not Necessary	288.96 FL	*- FL
4	1		*FRONT LH DOOR OUTER GARNISH	Not Necessary	488.22 FL	*- FL
5	1		*FRONT LH DOOR OUTER HANDLE	Not Necessary	488.22 FL	*- FL
6	1		*FRONT LH SIDE MIRROR	Not Necessary	999.55 FL	*- FL
7	1		*FRONT LH DOOR RUBBER	Torn	255.21 FL	*140.00 FL
8	1		*DOOR PILLAR LH	Repair	588.43 FL	*- FL
9	1		*FRONT LH FENDER	Not Necessary	800.32 FL	*- FL
10	1		*DOOR LETTERING	Necessary	30.00 FS	*30.00 FS
11	1		*LH HANDLE BASE	Twisted	334.20 FL	*211.00 FL
12	1		*FRONT LH OUTER HANDLE	Twisted	233.32 FL	*233.32 FL
13	1		*FRONT LH DOOR HINGE BOTTOM	Not Necessary	255.32 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,998.30	2,429.32
- List Item Discount on L Items 10.00/10.00% (\$\$)	696.83	239.93
Total Parts (\$\$)	6,301.47	2,189.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET POWER WINDOW }	New	120.00	80.00
2	TO TRANSFER DOOR }	New	80.00	0.00
3	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	700.00	300.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION	New	80.00	30.00
5	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	45.00	0.00
6	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS. PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES. FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	600.00	400.00
7	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	100.00	20.00
			Gross Labour Cost (S\$)	1,725.00
				830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >