

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD INV No. AC2101746

36 ROBINSON ROAD INV Date 18/03/2021

#16-01 CITY HOUSE Reference CC4/FCI20013862/Kes3q2

SINGAPORE 068877 Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJR 1253S

Insured Veh. SHD 3476A

Claim No. D20005019MFSH

Policy No. D-20094922MFSH

Accident Date 07/12/2020

Inspection Date 15/12/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CC4/FCI20013862/Kes3q2		
	36 ROBINSON RO #16-01 CITY HOUS	AD SESINGAPORE 068877	Date	e: 18/03/2021		
			Cod	e: FCl2		
1.		Policy Particulars :	- THIRD PARTY CLA	AIM		
	Insured Veh.	SHD 3476A	Veh. Inspected	SJR 1253S		
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00		
	Claim No.	D20005019MFSH	Excess (\$)	0.00		
	Assign From	CHRIS LIM	Assign Date	15/12/2020		
2.		Vehicle Partic	ulars & Condition			
	Make & Model	HYUNDAI AVANTE (A)	c.c	1591		
	Engine No.	HIDDEN	Year of Reg.	2009		
	Chassis No.	KMHDU41BR9U758979	Colour	METALLIC DARK BLUE		
	Odometer	309176 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	GOOD				
3.		Condition	ons of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	195/65 R15	FIRENZA	9 mm		
	L/H Front Tyre	195/65 R15	FIRENZA	9 mm		
	R/H Rear Tyre	195/65 R15	FIRENZA	9 mm		
	L/H Rear Tyre	195/65 R15	FIRENZA	9 mm		
4.		Description	on of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.		General	Information			
	Accident Date	07/12/2020	Inspection Date	15/12/2020		
	Survey held at	NGS MOTORSPORT PTE LTD				
		10 ANG MO KIO INDUSTRIAL PARK 2A #02-01 AMK AUTOPOINT SINGAPORE 568047				
5a.		Re	emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					
				· · · · · · · · · · · · · · · · · · ·		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 1253S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	TO REPAIR SEE LABOUR	985.50	-
1	REAR BOOT INNER LOCK	TO REPAIR SEE LABOUR	118.30	-
1	REAR BOOT TRUNK STRIKER	TO REPAIR SEE LABOUR	35.00	-
1	REAR BOOT OUTER GARNISH	SERVICEABLE	32.50	-
2	REAR BOOT HINGE LH/RH @\$132.00	TO REPAIR SEE LABOUR	264.00	-
1	TRUNK RUBBER	SERVICEABLE	79.30	-
1	TAILLAMP RH	SERVICEABLE	269.00	-
1	END PANEL	TO REPAIR SEE LABOUR	369.00	-
1	END PANEL GARNISH	SERVICEABLE	69.00	-
2	END PANEL EXTENSION RH/LH @\$161.00	TO REPAIR SEE LABOUR	322.00	-
1	REAR BUMPER	BUCKLED	447.00	447.00
1	REAR BUMPER REINFORCEMENT	CRACKED	270.20	270.20
1	REAR BUMPER SPONGE	CRACKED	149.00	149.00
2	REAR BUMPER RETAINER LH/RH @\$26.00	SERVICEABLE	52.00	-
3	REAR BUMPER LOWER BRACKET RH /LH & CENTER @ \$17.00	SERVICEABLE	51.00	-
1	REAR EXHAUAT	TO REPAIR SEE LABOUR	712.00	-
	LESS 20% DISCOUNT		-844.96	-173.24
			3,379.84	692.96
	SPECIAL NETT ITEMS			
1	PARKING SENSOR (SN)	SHORTED	280.00	200.00
1	REAR NO PLATE C/W CASING (SN)	SERVICEABLE	50.00	-
20	CLIPS ,REAR BOOT @\$3.50 (SN)	NOT NECESSARY	70.00	-
1	BADGE REAR BOOT (SN)	NECESSARY	34.00	34.00
1	AVANTE EMBLEM (SN)	NECESSARY	32.00	32.00

Report Ref No. CC4/FCI20013862/Kes3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	S EMBLEM (SN)	NECESSARY	20.00	20.00
			486.00	286.00
	<u>LABOUR</u>			
	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENTS/ATTACHMENTS .STRAIGHTEN CHASSIS MEMBER ,REPAIR/RESHAPE DENTED BODY PANEL INACCORDENCE WITH FACTORY SPECIFICATIONS.REPLACE /REPOSITION DAMAGED PARTS,REFIT ALIGN INTO REFIX ALL NECESSARY COMPONENTS/ ATTACHMENT.INCLUSIVE OF THE REPAIR OF REAR BOOT LID ,REAR BOOT INNER LOCK ,REAR BOOT TRUNK STRIKER ,REAR BOOT HINGE LH/RH,END PANEL,END PANEL EXTENSION RH/LH AND REAR EXHAUAT.		1,000.00	400.00
	TO SPRAY PAINTING .		1,000.00	540.00
	TO CHECK WIRING /PROPER FUNCTION ON LIGHT AND ETC.		50.00	10.00
			2,050.00	950.00
	GRAND TOTAL		5,915.84	1,928.96
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,550.00

Report Ref No. CC4/FCI20013862/Kes3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJR 1253S

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJR 1253S

RE-INSPECTION









