



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD TOYOTA ALTIS (SGQ4387K)
Date of Loss	2 August 2020
Time of Loss	15.10
Loss Description	SGQ4387K (TP) C/W STATIONARY SDM8889J (INSD)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="4901"/>
Nett Loss Amount	\$2,099.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#	SGQ4387K	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>16/01/2007</div> <div></div>
Mileage	<div>221397</div>	Age of Vehicle	13

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2006</div>
Make	TPVD	<div>TOYOTA</div>
	TOYOTA	<div></div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	OH BENG LYE	<div></div>
Date of Birth	31 December 1899	<div>dd/mm/</div> <div></div>

Model CATEGORY	TOTAL POLICY ALTIS INFORMATION	COROLLA ALTIS 1.6 AU ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="MR053ZEC107139187"/>
Engine No		<input type="text" value="3ZZ4625054"/>
Engine Capacity		<input type="text" value="1598"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="7000"/>

CATEGORY Age	FNOL INFORMATION 121	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/"/>
License Expiration Date		<input type="text" value="dd/mm/"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	BLK 10 NORTH BRIDGE RD #10-5109, 190010, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	S1577579C	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

21/01/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="25"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts






Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT BUMPER	Buckled	0	461	No		25			345.75	Reviewing
<input type="checkbox"/>		0	1		SET FRONT BUMPER CLIPS	Necessary	0	40	No		25			30	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER FOG LAMP - LH	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER REINFORCEMENT	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER SIDE RETAINER - LH	Damaged	0	36.3	No		25			27.23	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER SIDE RETAINER - RH	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT FENDER - LH	Bent	0	456	No		25			342	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT FENDER SPLASH SHIELD - LH	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		SET FRONT FENDER SPLASH SHIELD CLIP	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT GRILLE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT HEADLAMP - LH	Cracked	0	585.1	No		25			438.83	Reviewing
<input type="checkbox"/>		0	1		FRONT SUPPORT PANEL - LH	Repair	0	0	No		25			0	Deny

Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	0	400	0	0	Reviewing	
<input type="checkbox"/>		0		TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	0	400	0	0	Reviewing	
<input type="checkbox"/>		0		TO CHECK WIRING FUNCTIONS	0	20	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$2,003.81		
CATEGORY		ESTIMATE		ADJUSTED				
Spare Parts		\$0.00		\$1,183.81				
Labour		\$0.00		\$820.00				


Submit for Review

<<

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

- Add
- Approve
- Deny
- Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	FINAL LUMP SUM	Reviewing		1600		

Submit for Review