



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 8869S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER ASSY (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER SIDE COVER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-	-
			-	-
	<u>NETT ITEMS</u>			
1	FUEL TANK LID (PETROL STICKER)(N)	NECESSARY	15.00	15.00
	LESS 10% DISCOUNT		-	-1.50
			15.00	13.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER ASSY,REAR BUMPER SIDE COVER LH AND REAR FENDER LH.		1,200.00	720.00
	SPRAYPAINT.		600.00	500.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
	CHECK WIRING.		50.00	30.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REAR UPHOLSTERY.		120.00	60.00
			2,100.00	1,340.00
	GRAND TOTAL		2,115.00	1,353.50
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,353.50

Report Ref No. NS/INC20013865/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.