

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20013867/UVF3Q2

**Date:** 14/01/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30719819000	
<b>Claimant Vehicle No :</b>	SLV9288U	<b>Insured Vehicle No :</b>	GBB4837S	
Date of Loss:	13/12/2020	Nature of Claim:	TP	Claim No: SNM20D204864/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV9288U				
Make & Model:	JAGUAR XJ, 2.0 TSS SWB SR (A)	Engine No:	016068053718204PT		
Reg. Date:	29/12/2017 (Man. Year: 2016)	Chassis No:	SAJAC12M8GPW01838		
Colour:	Grey	Odometer:	34672 km		
Engine Capacity:	1999 cc				
Market Value/New Car Price:	N/A				
Sum Insured (S\$):	<b>Market Value/New Car Price</b>				

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/45ZR19	Rear Tyre Size:	245/45ZR19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	18,921.96	7,572.42	11,349.54	59.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	810.00	2,970.00	78.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,701.96</b>	<b>8,382.42</b>	<b>14,319.54</b>	<b>63.08</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>22,701.96</b>	<b>6,700.00</b>	<b>16,001.96</b>	<b>70.49</b>

### INSPECTION

Date of Assignment:	15/12/2020	
Date Inspected:	16/12/2020	Inspected At: Blk 15 Kaki Bukit Road 4 #01-53 Repairer: Zoom Autowerks Pte Ltd
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jan 2021)
<b>Parts:</b>	143	JAGUAR XJ 2.0 TSS SWB SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV9288U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut/Torn	2,492.80 FL	*2,492.80 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,188.40 FL	*- FL
3	1		*FRONT BUMPER INNER SPONGE	Not Necessary	580.60 FL	*- FL
4	1		*FRONT BUMPER CENTRE AIR-GRILLE	Not Necessary	396.40 FL	*- FL
5	1		*FRONT BUMPER SIDE GARNISH RH	Not Necessary	386.20 FL	*- FL
6	1		*FRONT BUMPER CHROME GARNISH RH	Not Necessary	321.50 FL	*- FL
7	1		*FRONT BUMPER DAY LIGHT RH	Not Necessary	496.70 FL	*- FL
8	1		*FRONT BUMPER INNER SUPPORT FRAME BRACKET	Cracked	296.30 FL	*245.00 FL
9	1		*FRONT BUMPER BRACKET RH	Not Necessary	175.40 FL	*- FL
10	1		*FRONT BUMPER MOUNT RH	Not Necessary	98.50 FL	*- FL
11	2		*FRONT BUMPER DISTANCE SENSOR	Not Necessary	765.20 FL	*- FL
12	1		*SET FRONT BUMPER DISTANCE SENSOR HOLDER	Not Necessary	145.80 FL	*- FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
14	1		*FRONT RADIATOR GRILLE CHROME	Not Necessary	391.80 FL	*- FL
15	1		*FRONT RADIATOR GRILLE BASE	Not Necessary	595.10 FL	*- FL
16	1		*FRONT RADIATOR GRILLE LOGO	Not Necessary	195.70 FL	*- FL
17	1		*FRONT HEADLAMP ASSY RH	Cracked	3,986.10 FL	*3,480.00 FL
18	1		*FRONT HEADLAMP BRACKET RH	Not Necessary	118.40 FL	*- FL
19	1		*FRONT BONNET ASSY	Not Necessary	3,186.40 FL	*- FL
20	1		*FRONT FENDER RH	Badly Dented	1,786.20 FL	*1,626.00 FL
21	1		*FRONT FENDER INNER SHIELD RH	Torn	498.10 FL	*450.00 FL
22	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*60.00 FL
23	1		*FRONT FENDER CHROME GARNISH RH	Not Necessary	328.70 FL	*- FL
24	1		*FRONT FENDER LAMP RH	Not Necessary	287.40 FL	*- FL
25	1		*FRONT WING MIRROR ASSY LH	Not Necessary	2,186.70 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>21,024.40</b>	<b>8,413.80</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>2,102.44</b>	<b>841.38</b>
<b>Total Parts (\$\$)</b>	<b>18,921.96</b>	<b>7,572.42</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,400.00	300.00
2	TO PUTTY,SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS	New	1,400.00	450.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
4	TO CONDUCT ALL WHEEL ALIGNMENT	New	280.00	0.00
5	TO DIAGNOSTIC & RESET TO SPECIFICATION	New	450.00	0.00
6	TO RUST PROOF AFFECTED AREAS	New	200.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,780.00</b>	<b>810.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**