

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG20013872/BGS3Q2

Date:

28/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900262679

Claimant Vehicle No : SMD4844E

Insured Vehicle No :

SMR2167R

Date of Loss: 14/12/2020

Nature of Claim:

TP

Claim No:

7820905473SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD4844E

Make & Model: TOYOTA ALPHARD, 2.5 SC CVT (A)

Engine No:

2ARJ086123

Reg. Date: 21/08/2018 (Man. Year: 2018)

Chassis No:

AGH300183784

Colour: Black

Odometer:

151947 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Rear Tyre Size:

235/50 R18

Front Left Side: Yokohama 5 mm

Rear Left Side:

Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side:

Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,850.80	4,357.07	12,493.73	74.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,380.00	2,230.00	3,150.00	58.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,230.80	6,587.07	15,643.73	70.37
Approved Total (Overridden) (S\$)		5,250.00		

(S\$)	22,230.80	5,250.00	16,980.80	76.38
+ GST 7.00/7.00% (S\$)	1,556.16	367.50	1,188.66	76.38
Nett Amount (S\$)	23,786.96	5,617.50	18,169.46	76.38
+ Loss of Use (2.0 x S\$80.00/day) (S\$)		160.00		
+ Car Rental (7.0 x S\$128.40/day) (S\$)		898.80		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,683.75		

INSPECTION

Date of Assignment: 15/12/2020

Date Inspected: 16/12/2020

Estimated Period of Repair: 7.0 days

Inspected At:

160 SIN MING DRIVE#01-14

Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,891.30 FL	*1,200.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	373.40 FL	*234.00 FL
3	1		*FRONT BUMPER SIDE CHROME MOULDING RH	Broken	452.30 FL	*372.50 FL
4	1		*FRONT BUMPER FOG LAMP RH	Broken	276.30 FL	*218.00 FL
5	1		*FRONT BUMPER FOG LAMP CHROME GARNISH RH	Cracked	425.60 FL	*142.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	447.80 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE	No such part	246.30 FL	*- FL
8	1		*FRONT BUMPER TOW CAP	No such part	82.00 FL	*- FL
9	1		*FRONT BUMPER PARKING SENSOR	O/S Scratched	508.00 FL	*100.00 FL
10	1		*FRONT GRILLE	Broken	1,921.40 FL	*789.60 FL
11	1		*FRONT FENDER RH	Repair	689.10 FL	*- FL
12	1		*FRONT FENDER INNER COWLING RH	Not Damaged	342.80 FL	*- FL
13	1		*FRONT FENDER LOWER GARNISH RH	Not Damaged	138.00 FL	*- FL
14	1		*FRONT FENDER SIDE GLASS MOULDING RH	Not Damaged	210.50 FL	*- FL
15	1		*HEADLAMP RH	Broken	3,214.23 FL	*1,800.00 FL
16	1		*HEADLAMP LOWER BRACKET RH	No such part	228.00 FL	*- FL
17	1		*RADAR SENSOR	Not Damaged	2,984.60 FL	*- FL
18	1		*FRONT LOWER ARM RH	Not Damaged	369.00 FL	*- FL
19	1		*FRONT SHOCK ABSORBER RH	Not Damaged	326.00 FL	*- FL
20	1		*FRONT KNUCKLE ARM RH	Repair	423.00 FL	*- FL
21	1		*FRONT KNUCKLE ARM BEARING RH	Repair	410.50 FL	*- FL
22	1		*FRONT STEERING RACK	Not Damaged	2,864.00 FL	*- FL
23	1		*WIPER WASHER TANK	Not Necessary	299.60 FL	*- FL
24	1		*WIPER WASHER TANK MOTOR	Not Damaged	144.00 FL	*- FL
25	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
26	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*FRONT BUMPER SIDE CHROME MOULDING CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*FRONT BUMPER FOG LAMP CHROME GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
30	2		*FRONT BUMPER PARKING SENSOR SEAL	Necessary (1 PCS ONLY)	90.00 FS	*45.00 FS
31	2		*FRONT BUMPER SIDE CHROME MOULDING RH	Not Necessary	160.00 FS	*- FS
32	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
33	1		*FRONT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
34	1		*FRONT FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
35	1		*FRONT SIDE GLASS SEALANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT SIDE GLASS INNER SEAL	Not Necessary	80.00 FS	*- FS
37	1		*FRONT SIDE GLASS PRIMER AND CLEANER	Not Necessary	60.00 FS	*- FS
38	1		*FRONT ALLOY RIM	Cut	950.00 FS	*550.00 FS
39	1		*FRONT TYRE	Not Damaged	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	21,667.73	5,571.10
- List Item Discount on L Items 25.00/25.00% (\$)	4,816.93	1,214.03
Total Parts (\$)	16,850.80	4,357.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R FRONT BUMPER PARKING SENSOR	New	100.00	60.00
2	R&R RADAR SENSOR	New	200.00	0.00
3	R&R FRONT SIDE GLASS	New	250.00	0.00
4	R&R FRONT UNDER CARRIAGE	New	300.00	150.00
5	R&R FRONT TYRE & BALANCING	New	250.00	60.00
6	WHEEL ALIGNMENT	New	180.00	60.00
7	RADAR SENSOR ALIGNMENT	New	300.00	300.00
8	CHECK WIRING	New	200.00	50.00
9	DIAGNOTIC RESET FAULT CODE	New	300.00	150.00
10	UPHOLSTERY	New	300.00	0.00
11	PANEL BEAT	New	1,400.00	1,000.00
12	RUST PROOFING	New	200.00	0.00
13	SPRAY PAINTING	New	1,400.00	400.00
Gross Labour Cost (S\$)			5,380.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >