Adjuster Report Page 1 of 3

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20013873/KTD3Q2

**Date:** 15/03/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700093832

Claimant
Vehicle No: Insured Vehicle No: SLV3546P

Date of Loss: 11/12/2020 Nature of Claim: TP Claim No: 1871576301SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMU8473B

Make & Model: MAZDA 2, 1.5 (A) Engine No: P520603623

Reg. Date: 31/08/2020 (Man. Year: 2019) Chassis No: JM6DJ2HAA01300492

Colour: Metallic Grey Odometer: 4909 km

Engine Capacity: 1496 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15
Front Left Side: Dunlop 9 mm Rear Left Side: Dunlop 9 mm
Front Right Side: Dunlop 9 mm
Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,110.00	2,683.40	1,426.60	34.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	1,070.00	360.00	25.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,540.00	3,753.40	1,786.60	32.25

INSPECTION

Date of Assignment: 15/12/2020

Date Inspected: 16/12/2020 Inspected At: King's Auto Spray Paint Pte Ltd (HQ)

BLK 160 SIN MING DRIVE #05-10

SIN MING AUTOCARE Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

### **Recommended Parts**

OUTER           5         2         *FRONT BONNET RUBBER CLIPS INNER         Necessary         10.00 FL         *10.00 FL         *874.00 FL         *50.00 FL         *50.00 FL         *50.00 FL         *50.00 FL         *50.00 FL         *50.00 FL         *10.00 FL         *11.00 FL         *50.00 FL         *20.00 FL         *12.00 FL         *25.00 FL         *12.00 FL         *25.00	No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
3	1	1		*FRONT BONNET	Buckled	738.00 FL	*738.00 FL
4	2	1		*FRONT BONNET OUTER RUBBER	Serviceable	60.00 FL	*-FL
Section   Sect	3	1		*FRONT BONNET INNER RUBBER	Serviceable	36.00 FL	*-FL
INNER	4	18			Necessary	90.00 FL	*90.00 FL
7         1         *FRONT BUMPER         Buckled         874.00 FL         *874.8           8         10         *FRONT BUMPER TOP CLIPS         Necessary         50.00 FL         *50.00 FL           9         1         *FRONT BUMPER SIDE RETAINERS         O/s Distorted         36.00 FL         *18.           10         2         *FRONT BUMPER SIDE COVER         Serviceable         90.00 FL         *18.           11         1         *FRONT BUMPER LOWER GRILLE         Cracked         93.00 FL         *93.00 FL         *93.00 FL         *93.00 FL         *93.00 FL         *193.00 FL         *10.00 FL         *25.00 FL         *26.00 FL         *34.00 FL <t< td=""><td>5</td><td>2</td><td></td><td></td><td>Necessary</td><td>10.00 FL</td><td>*10.00 FL</td></t<>	5	2			Necessary	10.00 FL	*10.00 FL
8         10         *FRONT BUMPER TOP CLIPS         Necessary         50.00 FL         *50.00 FL         *50.00 FL         *50.00 FL         *50.00 FL         *50.00 FL         *50.00 FL         *18.           10         2         *FRONT BUMPER SIDE COVER         Serviceable         90.00 FL         *18.           11         1         *FRONT BUMPER SIDE COVER         Serviceable         90.00 FL         *18.           12         1         *FRONT BUMPER LOWER GRILLE         Cracked         93.00 FL         *93.           12         1         *FRONT BUMPER BEAM         Repair         50.00 FL         *93.           13         2         *FRONT BUMPER SPONGE INNER         Cracked         128.00 FL         *128.           15         5         *FRONT BUMPER SPONGE INNER         Cracked         128.00 FL         *25.           16         1         *FRONT BUMPER CLIPS         Necessary         25.00 FL         *25.           16         1         *FRONT GRILLE         Dented         91.00 FL         *91.           17         1         *FRONT GRILLE RIVET         Necessary         50.00 FL         *50.           19         1         *FRONT GRILLE SIDE MLDG         O/s Cracked         334.00 FL         *5	6	1		*FRONT BONNET LOCK	Repair	179.00 FL	*-FL
9 1 *FRONT BUMPER SIDE RETAINERS O/s Distorted 36.00 FL *18. 10 2 *FRONT BUMPER SIDE COVER Serviceable 90.00 FL 11 1 *FRONT BUMPER LOWER GRILLE Cracked 93.00 FL *93. 12 1 *FRONT BUMPER BEAM Repair 526.00 FL 13 2 *FRONT BUMPER BRACKETS Repair 50.00 FL 14 1 *FRONT BUMPER SPONGE INNER Cracked 128.00 FL *128. 15 5 *FRONT BUMPER CLIPS Necessary 25.00 FL *25. 16 1 *FRONT GRILLE DGO Necessary 34.00 FL *91. 17 1 *FRONT GRILLE LOGO Necessary 50.00 FL *50. 18 5 *FRONT GRILLE RIVET Necessary 50.00 FL *50. 19 1 *FRONT GRILLE SIDE MLDG O/s Cracked 334.00 FL *167. 20 1 *FRONT GRILLE SIDE MLDG O/s Cracked 334.00 FL *581. 21 2 *FRONT HEAD LAMP Os Mtg Cracked/Ns Serviceable 70.00 FL *581. 22 1 *FRONT SUPPORT PANEL Cracked 374.00 FL *374. 23 1 *FRONT NUMBER PLATE Scorched 30.00 FS *25. F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 5,130.00 3,348.  - List Item Discount on L Items 20.00/20.00% (S\$) 1,020.00 664.	7	1		*FRONT BUMPER	Buckled	874.00 FL	*874.00 FL
10   2	8	10		*FRONT BUMPER TOP CLIPS	Necessary	50.00 FL	*50.00 FL
11	9	1		*FRONT BUMPER SIDE RETAINERS	O/s Distorted	36.00 FL	*18.00 FL
12       1       *FRONT BUMPER BEAM       Repair       526.00 FL         13       2       *FRONT BUMPER BRACKETS       Repair       50.00 FL         14       1       *FRONT BUMPER SPONGE INNER       Cracked       128.00 FL       *128.00 FL       *25.00 FL       *34.00 FL       *34.00 FL       *34.00 FL       *34.00 FL       *50.00 FL       *50.00 FL       *50.00 FL       *50.00 FL       *50.00 FL       *581.00 FL	10	2		*FRONT BUMPER SIDE COVER	Serviceable	90.00 FL	*- FL
13   2	11	1		*FRONT BUMPER LOWER GRILLE	Cracked	93.00 FL	*93.00 FL
14       1       *FRONT BUMPER SPONGE INNER       Cracked       128.00 FL       *128.00 FL       *25.00 FL       *25.00 FL       *25.00 FL       *25.00 FL       *25.00 FL       *25.00 FL       *91.00 FL       *91.00 FL       *91.00 FL       *91.00 FL       *91.00 FL       *34.00 FL       *34.00 FL       *34.00 FL       *34.00 FL       *50.00 FL       *50.	12	1		*FRONT BUMPER BEAM	Repair	526.00 FL	*-FL
15	13	2		*FRONT BUMPER BRACKETS		50.00 FL	*-FL
16       1       *FRONT GRILLE       Dented       91.00 FL       *91.         17       1       *FRONT GRILLE LOGO       Necessary       34.00 FL       *34.         18       5       *FRONT GRILLE RIVET       Necessary       50.00 FL       *50.         19       1       *FRONT GRILLE SIDE MLDG       O/s Cracked       334.00 FL       *167.         20       1       *FRONT HEAD LAMP       Os Mtg Cracked/Ns Serviceable       1,162.00 FL       *581.         21       2       *FRONT SUPPORT PANEL       Cracked       374.00 FL       *374.         22       1       *FRONT NUMBER PLATE       Scorched       30.00 FS       *25.         F=Franchise part. S=SpcNett. L=ListItemDisc.       Sub Total (S\$)       5,130.00       3,348.         - List Item Discount on L Items 20.00/20.00% (S\$)       1,020.00       664.	14	1		*FRONT BUMPER SPONGE INNER	Cracked	128.00 FL	*128.00 FL
17       1       *FRONT GRILLE LOGO       Necessary       34.00 FL       *34.01 FL       *34.00 FL       *34.00 FL       *34.00 FL       *34.00 FL       *50.00 FL       *50.00 FL       *50.00 FL       *50.00 FL       *50.00 FL       *50.00 FL       *167.00 FL       *167.00 FL       *167.00 FL       *162.00 FL       *581.00 FL       *374.00 FL	15	5		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
18       5       *FRONT GRILLE RIVET       Necessary       50.00 FL       *50.00 FL       *10.00 FL       *10.00 FL       *10.00 FL       *10.00 FL       *50.00 FL       *50.00 FL       *50.00 FL       *10.00 FL       *10.00 FL       *50.00 FL       *30.00 FL       *374.00 FL	16	1		*FRONT GRILLE	Dented	91.00 FL	*91.00 FL
19 1 *FRONT GRILLE SIDE MLDG O/s Cracked 334.00 FL *167. 20 1 *FRONT HEAD LAMP Os Mtg Cracked/Ns Serviceable 1,162.00 FL *581. 21 2 *FRONT HEAD LAMP GARNISH Serviceable 70.00 FL 22 1 *FRONT SUPPORT PANEL Cracked 374.00 FL *374. 23 1 *FRONT NUMBER PLATE Scorched 30.00 FS *25. F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 5,130.00 3,348.  - List Item Discount on L Items 20.00/20.00% (S\$) 1,020.00 664.  Total Parts (S\$) 4,110.00 2,683.	17	1		*FRONT GRILLE LOGO	Necessary	34.00 FL	*34.00 FL
20 1 *FRONT HEAD LAMP Serviceable 1,162.00 FL *581. 21 2 *FRONT HEAD LAMP GARNISH Serviceable 70.00 FL 22 1 *FRONT SUPPORT PANEL Cracked 374.00 FL *374. 23 1 *FRONT NUMBER PLATE Scorched 30.00 FS *25. F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 5,130.00 3,348.  - List Item Discount on L Items 20.00/20.00% (S\$) 1,020.00 664.  Total Parts (S\$) 4,110.00 2,683.	18	5		*FRONT GRILLE RIVET	Necessary	50.00 FL	*50.00 FL
Serviceable	19	1		*FRONT GRILLE SIDE MLDG	O/s Cracked	334.00 FL	*167.00 FL
22       1       *FRONT SUPPORT PANEL       Cracked       374.00 FL       *374.20 FL       *374.20 FL       *25.70 FL	20	1		*FRONT HEAD LAMP		1,162.00 FL	*581.00 FL
23 1 *FRONT NUMBER PLATE Scorched 30.00 FS *25. F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 5,130.00 3,348.  - List Item Discount on L Items 20.00/20.00% (S\$) 1,020.00 664.  Total Parts (S\$) 4,110.00 2,683.	21	2		*FRONT HEAD LAMP GARNISH	Serviceable	70.00 FL	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 5,130.00 3,348.  - List Item Discount on L Items 20.00/20.00% (S\$) 1,020.00 664.  Total Parts (S\$) 4,110.00 2,683.	22	1		*FRONT SUPPORT PANEL	Cracked	374.00 FL	*374.00 FL
Sub Total (S\$) 5,130.00 3,348 List Item Discount on L Items 20.00/20.00% (S\$) 1,020.00 664.  Total Parts (S\$) 4,110.00 2,683.	23	1		*FRONT NUMBER PLATE	Scorched	30.00 FS	*25.00 FS
- List Item Discount on L Items 20.00/20.00% (S\$) 1,020.00 664.  Total Parts (S\$) 4,110.00 2,683.	F=Fra	anchise	part. S=S	pcNett. L=ListItemDisc.			
Total Parts (S\$) 4,110.00 2,683.							3,348.00
				- List Item Discou	nt on L Items 20.00/20.00% (S\$)	1,020.00	664.60
					Total Parts (S\$)	4,110.00	2,683.40
Report was unsubmitted during this print-out.				Report was unsubmitte	d during this print-out.		

Adjuster Report Page 3 of 3

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CHECK WIRING	New	30.00	20.00
2	TO RENEW THE ABOVE MENTIONED PARTS, KNOCKING, CUTTING, WELDING & FRONT DAMAGED PARTS	New <b>\$ STRAIGHTEN</b>	700.00	500.00
3	SPRAY PAINTING	New	700.00	550.00
		Gross Labour Cost (S\$)	1,430.00	1,070.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >