

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013874/T1BA3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900234418
Claimant Vehicle No :	SHA1251K	Insured Vehicle No :	SMQ1067H
Date of Loss:	14/12/2020	Nature of Claim:	TP
		Claim No:	9317550590SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1251K		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRS055703
Reg. Date:	05/07/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU803561141
Colour:	Blue	Odometer:	364768 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	707.70	0.00	707.70	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	940.00	240.00	20.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,887.70	940.00	947.70	50.20
+ GST 7.00/7.00% (S\$)	132.14	65.80	66.34	50.20

Nett Amount (S\$)	2,019.84	1,005.80	1,014.04	50.20
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.40/day) (S\$)		501.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,709.40		
Global Sum Settlement (S\$)		1,700.00		

INSPECTION

Date of Assignment: 15/12/2020

Date Inspected: 16/12/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	458.60 FL	*- FL
2	10		*BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER LH	Not Necessary	112.70 FL	*- FL
4	1		*TOWING COVER	Not Necessary	82.70 FL	*- FL
5	1		*REAR BUMPER MAT	Not Necessary	50.00 FS	*- FS
6	1		*PETROL STICKER	Not Necessary	15.00 FS	*- FS
7	1		*REVERSE SENSOR	Not Necessary	135.70 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	876.70	0.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	169.00	0.00
Total Parts (\$\$)	707.70	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	480.00
2	SPRAY PAINTING	New	500.00	400.00
3	WIRING	New	60.00	0.00
4	TUFF KOTE	New	60.00	30.00
5	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (S\$)			1,180.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >