

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III20013879/AEA3Q2

Date:

20/12/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MCV0000399_01

Claimant Vehicle No : SMV3109G**Insured Vehicle No :**

GBE5899R

Date of Loss: 12/12/2020

Nature of Claim:

TP

Claim No:

MCV2020D0002700

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMV3109G**

Make & Model: MERCEDES-BENZ S300L, 3.0 (A)

Engine No:

27294630747256

Reg. Date: 14/01/2008 (Man. Year: 2007)

Chassis No:

WDD2211542A175556

Colour: Grey

Odometer:

90589 km

Engine Capacity: 2997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40 R19

Rear Tyre Size:

255/40 R19

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,263.79	10,523.81	19,739.98	65.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,310.00	1,790.00	3,520.00	66.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,573.79	12,313.81	23,259.98	65.39
Approved Total (Overridden) (S\$)		9,850.00		

(S\$)	35,573.79	9,850.00	25,723.79	72.31
+ GST 7.00/7.00% (S\$)	2,490.17	689.50	1,800.67	72.31
Nett Amount (S\$)	38,063.96	10,539.50	27,524.46	72.31
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		11,546.95		
Global Sum Settlement (S\$)		11,540.00		

INSPECTION

Date of Assignment: 15/12/2020

Date Inspected: 15/12/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)
 No.1, Kaki Bukit Ave 6, #02-22 Autobay
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2021)
Parts:	143	MERCEDES-BENZ S300L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV3109G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	3,088.00 FL	*- FL
2	1		*FRONT BONNET LOCK LOWER	Not Necessary	345.00 FL	*- FL
3	1		*FRONT BONNET LOCK UPPER	Not Necessary	325.00 FL	*- FL
4	1		*FRONT HEADLAMP LOWER BRACKET	Cracked	355.00 FL	*148.00 FL
5	1		*FRONT GRILLE ASSY	Cracked	1,450.00 FL	*845.00 FL
6	1		*FRONT BUMPER	Distorted	2,050.00 FL	*1,845.00 FL
7	1		*FRONT BUMPER SIDE BRACKET	O/S Damaged	397.00 FL	*198.50 FL
8	1		*FRONT BUMPER CENTRE BRACKET	Cracked	245.90 FL	*245.90 FL
9	1		*FRONT BUMPER LAMP -RH	Cracked	495.00 FL	*495.00 FL
10	1		*FRONT BUMPER FOG LAMP COVER	Deformed	238.00 FL	*238.00 FL
11	1		*FRONT BUMPER INNER SPONGE CENTRE	Cracked	343.00 FL	*192.00 FL
12	1		*FRONT BUMPER INNER SPONGE SIDE	O/S Cracked	491.60 FL	*71.00 FL
13	1		*FRONT BUMPER LOWER GRILLE	Deformed	286.00 FL	*173.00 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	887.00 FL	*887.00 FL
15	1		*FRONT BUMPER INNER GARNISH	Not Necessary	365.00 FL	*- FL
16	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	277.00 FL	*- FL
17	1		*FRONT BUMPER SPRAY NOZZLE PEN	Not Necessary	380.00 FL	*- FL
18	1		*FRONT BUMPER SPRAY NOZZLE COVER	Missing	178.00 FL	*178.00 FL
19	2		*FRONT BUMPER PDC SENSOR -CENTRE	Not Necessary	767.00 FL	*- FL
20	1		*FRONT BUMPER PDC SIDE SENSOR -RH	Damaged	383.50 FL	*383.50 FL
21	1		*FRONT BUMPER UNDERCOVER	Not Necessary	425.00 FL	*- FL
22	1		*FRONT BUMPER TOWING COVER	Not Necessary	86.50 FL	*- FL
23	2		*FRONT BUMPER CHROME MOULDING -SIDE	Necessary	770.00 FL	*296.00 FL
24	1		*FRONT BUMPER CHROME MOULDING -CENTRE	Necessary	396.70 FL	*195.00 FL
25	1		*FRONT FENDER -RH	Distorted	1,555.00 FL	*1,084.00 FL
26	1		*FRONT FENDER INNER SHIELD	Torn	296.00 FL	*296.00 FL
27	1		*FRONT SUPPORT PANEL	Not Necessary	1,458.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*ENGINE UNDERCOVER	Not Necessary	458.20 FL	*- FL
29	1		*FRONT HORN	Not Necessary	98.50 FL	*- FL
30	1		*FRONT NUMBER PLATE GARNISH	Not Necessary	185.90 FL	*- FL
31	1		*AIR CON CONDENSER	Not Necessary	1,107.96 FL	*- FL
32	1		*RADIATOR	Not Necessary	1,287.85 FL	*- FL
33	2		*RADIATOR AIR GUIDE	Not Necessary	731.60 FL	*- FL
34	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
35	1		*FRONT NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
36	1		*FRONT HEADLAMP (AFTERMARKET)	O/S Smashed	6,500.00 FS	*3,500.00 FS
37	1		*FRONT TYRE	Not Necessary	800.00 FS	*- FS
38	1		*FRONT WHEEL RIM	Not Necessary	2,850.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	32,484.21	11,300.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,220.42	777.09
Total Parts (\$\$)	30,263.79	10,523.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT,WELD ,REALIGN AND ALIGNE ALL PARTS	New	2,000.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	1,800.00	750.00
3	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING AND ENCODING	New	400.00	120.00
4	TO REMOVE AND REFIT FRONT SENSOR AND DISTANCE SETTLING	New	180.00	60.00
5	TO CONDUCT WHEEL ALIGNMENT	New	180.00	0.00
6	TO REMOVE/REFIT FRONT CONDENSER AND TOP UP GAS	New	150.00	0.00
7	TO APPLY UNDERCOATING	New	200.00	60.00
8	TO DIAGNOSE ERASE FAUL MEMORY AFTER REPAIR	New	400.00	0.00
Gross Labour Cost (S\$)			5,310.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >