

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQI20013888/UTD3E2
Date: 10/03/2021

REFERENCE

Handling Insurer: EQ Insurance Company Ltd Policy No:
Claimant Vehicle No : SLF1974J **Insured Vehicle No :** GBD4590S
Date of Loss: 11/12/2020 Nature of Claim: TP Claim No: DM20HO01888/JT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF1974J**
Make & Model: MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A) Engine No: P520370580
Reg. Date: 17/08/2016 (Man. Year: 2016) Chassis No: JM6BM42A8G0344254
Colour: Blue Odometer: 63750 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,068.10	880.90	187.20	17.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	730.00	430.00	300.00	41.10
Paintwork Labour	600.00	400.00	200.00	33.33
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,398.10	1,710.90	687.20	28.66
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	2,398.10	1,350.00	1,048.10	43.71
+ GST 7.00/7.00% (S\$)	167.87	94.50	73.37	43.71
Nett Amount (S\$)	2,565.97	1,444.50	1,121.47	43.71

INSPECTION

Date of Assignment: 16/12/2020 Present Location: Progressive Car Care Pte Ltd (HQ)
Date Inspected: 05/01/2021 Inspected At: Progressive Car Care Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Mar 2021)
Parts: 143	MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF1974J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*REAR BUMPER WITH LOWER GARNISH; BLACK (WCP)	Dented / Deformed	370.00 F	*370.00 F
2	1	NA	*REAR BUMPER TOW COVER - LH (WCP)	Missing	29.00 F	*29.00 F
3	2	NA	*REAR BUMPER SIDE HOLDER - LH/RH (WCP)	Not Necessary	32.00 F	*- F
4	10	NA	*REAR BUMPER CLIPS (WCP)	Necessary	30.00 F	*30.00 F
5	1	NA	*REAR BUMPER REINFORCEMENT (WCP)	Dented	190.00 F	*190.00 F
6	4	NA	*REAR BUMPER SENSOR (WCP)	Shorted	320.00 F	*200.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	971.00	819.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	97.10	61.90
Total Parts (\$\$)	1,068.10	880.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	600.00	400.00
<u>Labour Items</u>				
2	TO KNOCK OUT DENTS ON REAR PANEL; CUT/WELD & REPLACE ACCIDENT PARTS	New	500.00	300.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
5	TO REMOVE; REFIT REAR GARNISH	New	80.00	60.00
6	TO TUFF-KOTE	New	30.00	0.00
			Gross Labour Cost (\$)	1,330.00
				830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >