

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG20013894/GTF3Q2**Date:** 09/04/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993856
Claimant
Vehicle No : FBR372H **Insured Vehicle No :** SLV2773G
Date of Loss: 10/12/2020 Nature of Claim: TP Claim No: 2646350024SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBR372H**
Make & Model: HONDA ACCORD, 1.6 (M) Engine No: KF61E1013870
Reg. Date: 06/02/2020 (Man. Year: 2019) Chassis No: MH1KF6117KK013895
Colour: Red Odometer: 0 km
Engine Capacity: 149 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80-14 Rear Tyre Size: 130/70-13
Front Left Side: Federal 6 mm Rear Left Side: Federal 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/12/2020
Date Inspected: 16/12/2020 Inspected At: Ss Motoring (HQ)
1084 SERANGOON ROAD
Singapore 328186

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT FORK ASSY	*Check	0.00 F	*- F	
2	1		*FRONT FORK OIL SEAL	*Check	0.00 F	*- F	
3	1		*FRONT FORK OIL	*Check	0.00 F	*- F	
4	1		*FRONT HEADLAMP	*Check	0.00 F	*- F	
5	1		*FRONT WING MIRROR	Cut	0.00 F	*- F	
6	1		*FRONT LH SIGNAL LAMP	Distorted	0.00 F	*- F	
7	1		*ERP UNIT	Cut	0.00 F	*- F	
8	1		*STEERING STEM	*Check	0.00 F	*- F	
9	1		*STEERING CONE AND BEARING	*Check	0.00 F	*- F	
10	1		*HANDLE BAR	*Check	0.00 F	*- F	
11	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F	
12	1		*CLUTCH LEVER	Cut	0.00 F	*- F	
13	1		*SIDE FAIRING	Cut	0.00 F	*- F	
14	1		*SIDE FAIRING INNER GARNISH	*Check	0.00 F	*- F	
15	1		*FAIRING SHIELD	Cracked	0.00 F	*- F	
16	1		*FRONT TOP FAIRING INNER GARNISH	Cracked	0.00 F	*- F	
17	1		*CENTER FAIRING	*Check	0.00 F	*- F	
18	1		*REAR FAIRING	Cut	0.00 F	*- F	
19	1		*FAIRING LOWER	Cracked	0.00 F	*- F	
20	1		*STEP BOARD	Cracked	0.00 F	*- F	
21	1		*AIR FILTER COVER	Cut	0.00 F	*- F	
22	1		*SIDE STAND	Cut	0.00 F	*- F	
23	1		*MAIN STAND	Cut	0.00 F	*- F	
24	1		*CLUTCH ENGINE COVER	Cut	0.00 F	*- F	
25	1		*REAR FOOT REST	Cut	0.00 F	*- F	
26	1		*REAR FOOT REST BRACKET	Cut	0.00 F	*- F	
27	1		*REAR SUB FRAME	*Check	0.00 F	*- F	
28	1		*REAR TAILLAMP	*Check	0.00 F	*- F	
29	1		*PILLION HANDLE	Cut	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >