

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013896/DTF3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMHCSNA00004942001	
Claimant Vehicle No : SLU9362T	Insured Vehicle No : SMP2232X	
Date of Loss: 12/12/2020	Nature of Claim: TP	Claim No: SNM20D204868/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU9362T		
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Engine No:	1NZ8359969
Reg. Date:	18/12/2017 (Man. Year: 2017)	Chassis No:	NHP1707107333
Colour:	Yellow	Odometer:	178806 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,033.39	2,879.47	5,153.92	64.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	960.00	1,640.00	63.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,633.39	3,839.47	6,793.92	63.89
Approved Total (Overridden) (\$\$)		3,050.00		
(\$\$)	10,633.39	3,050.00	7,583.39	71.32
+ GST 7.00/7.00% (\$\$)	744.34	213.50	530.84	71.32
Nett Amount (\$\$)	11,377.73	3,263.50	8,114.23	71.32

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 18/12/2020 Inspected At:

C.S. Ong Auto Pte Ltd (AMK)
10 Ang Mo Kio Industrial Park 2A,
#02-16, AMK Auto Point
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU9362T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Not Necessary	593.60 FL	*- FL
2	1	*SET FRONT BUMPER CLIPS	Not Necessary	35.00 FL	*- FL
3	1	*FRONT BUMPER LOWER GARNISH	Not Necessary	867.90 FL	*- FL
4	1	*FRONT RH DOOR	Dented	1,831.80 FL	*1,288.10 FL
5	1	*FRONT RH DOOR INNER WEATHERSTRIP RUBBER	Serviceable	381.80 FL	*- FL
6	1	*FRONT RH FENDER	Dented	790.50 FL	*790.50 FL
7	1	*FRONT RH FENDER SHIELD	Not Necessary	209.50 FL	*- FL
8	1	*SET FRONT RH FENDER SHIELD CLIPS	Not Necessary	35.00 FL	*- FL
9	1	*FRONT RH ABSORBER	Distorted	561.00 FL	*417.00 FL
10	1	*FRONT RH KNUCKLE	Distorted	642.00 FL	*498.00 FL
11	1	*SET FRONT RH WHEEL BEARING & HUB	Damaged	396.45 FL	*165.70 FL
12	1	*FRONT RH FOGLAMP	Not Necessary	286.20 FL	*- FL
13	1	*FRONT RH FOGLAMP COVER	Not Necessary	208.30 FL	*- FL
14	1	*FRONT RH HEADLAMP	Not Necessary	1,395.00 FL	*- FL
15	1	*FRONT RH SIDE MIRROR ASSEMBLY	Not Necessary	863.80 FL	*- FL
16	1	*FRONT LOWER ARM RH	Distorted	480.00 FL	*480.00 FL
17	1	*FRONT RH TYRE	Not Necessary	350.00 FS	*- FS
18	1	*FRONT RH WHEEL CAP	Cut	500.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,427.85	3,789.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,394.46	909.83
Total Parts (\$\$)	8,033.39	2,879.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS ON ALL FRONT AFFECTED AREAS TO FACILITATE REPAIR AND TO REPLACE ALL BACK ONCE REPAIR IS DONE	New	200.00	60.00
2	TO PANEL BEAT ALL AFFECTED AREAS ,REPLACE NEW PARTS AND REALIGN ALL ABOVE	New	1,000.00	400.00
3	TO PUTTY AND RESPRAY NEW PAINTWORK ON ALL FRONT AFFECTED AREAS	New	1,000.00	400.00
4	TO CONDUCT WHEEL ALIGNMENT	New	100.00	60.00
5	TO CHECK ALL WIRING SYSTEMS ON ALL AFFECTED AREAS	New	150.00	0.00
6	TO APPLY ANTI-RUST AGENT & COATING ON ALL AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (\$\$)			2,600.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >