

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20013897/KQD3Q2

Date: 09/02/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD	Policy No: 0999993880
Date of Loss: 04/12/2020	Nature of Claim: OD Claim No: 8849829089SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ8965L	Engine No: CXH179395
Make & Model: VOLKSWAGEN T6 VAN, 2.0 TDI NWB DSG (A)	Chassis No: WV1ZZZ7HZKH032202
Reg. Date: 25/09/2019 (Man. Year: 2018)	Odometer: 34807 km
Colour: Red	
Engine Capacity: 1968 cc	
Market Value/New Car Price: S\$65,000.00	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 215/60R16	Rear Tyre Size: 215/60R16
Front Left Side: Achilles 6 mm	Rear Left Side: Goodyear 9 mm
Front Right Side: Achilles 6 mm	Rear Right Side: Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,491.20	8,822.90	1,668.30	15.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,170.00	1,280.00	52.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,941.20	9,992.90	2,948.30	22.78
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	11,541.20	8,592.90	2,948.30	25.55
+ GST 7.00/7.00% (S\$)	807.88	601.50	206.38	25.55
Nett Amount (S\$)	12,349.08	9,194.40	3,154.68	25.55

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 16/12/2020 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Buckled	1,180.00 F	*1,180.00 F
2	2		*BONNET HINGES-LH/RH (WCP)	Repair	190.00 F	*- F
3	1		*BONNET LOWER LOCK (WCP)	Repair	115.00 F	*- F
4	1		*SUPPORT PANEL (WCP)	Cracked	780.00 F	*780.00 F
5	1		*BRACE PANEL (WCP)	Distorted	155.00 F	*155.00 F
6	1		*FRONT GRILLE LOGO (WCP)	Missing	75.00 F	*75.00 F
7	1		*FRONT GRILLE LOGO PLATE (WCP)	Missing	35.00 F	*35.00 F
8	1		*FRONT GRILLE LOGO BASE (WCP)	Cracked	58.00 F	*58.00 F
9	2		*HEADLAMP ASSY-LH/RH (WCP)	Cracked	970.00 F	*970.00 F
10	1		*FRONT BUMPER (WCP)	Buckled	880.00 F	*880.00 F
11	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	520.00 F	*520.00 F
12	1		*FRONT BUMPER REINFORCEMENT COVER (WCP)	Serviceable	198.00 F	*- F
13	2		*FRONT BUMPER BRACKETS-RH/LH (WCP)	Serviceable	90.00 F	*- F
14	2		*FRONT BUMPER SIDE RETAINER-LH/RH (WCP)	Distorted	56.00 F	*56.00 F
15	1		*FRONT BUMPER SPONGE (WCP)	Serviceable	50.00 F	*- F
16	2		*FRONT BUMPER MOULDING-RH/LH (WCP)	No such part	130.00 F	*- F
17	1		*AIR-CON CONDENSER (WCP)	Bent	850.00 F	*850.00 F
18	1		*RADIATOR ASSY (INNER) (WCP)	Bent	385.00 F	*385.00 F
19	1		*RADIATOR ASSY (OUTER) (WCP)	Punctured	580.00 F	*580.00 F
20	1		*INTER-COOLER ASSY (WCP)	Serviceable	680.00 F	*- F
21	2		*RADIATOR COOLANT (TIN)	Necessary	120.00 FS	*50.00 FS
22	1		*FRONT NUMBER PLATE	Dented	40.00 FS	*40.00 FS
23	1		*RADIATOR FAN MOTOR ASSY (Supplementary)	Cracked	1,380.00 F	*1,380.00 F
24	1		*GUIDE-RH (Supplementary)	Cracked	35.00 F	*35.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$)	9,552.00	8,029.00
+ Margin on L,N Items 10.00/10.00% (\$)	939.20	793.90
Total Parts (\$)	10,491.20	8,822.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX AIR-CON CONDENSOR,RADIATOR,INTER COOLER ASSY AND REFILL AIR-CON GAS	New	150.00	100.00
2	TO PANEL BEAT AND STRAIGHTEN FRONT CHASIS FRAME,FRONT LOWER CROSS MEMBER,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME	New	1,000.00	500.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	400.00
5	TO SUPPLY ARTWORK AND PASTE STICKER ON BONNET	New	220.00	150.00
*Check				
Gross Labour Cost (\$\$)			2,450.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >