

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013898/R1TD3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00018112003
Claimant Vehicle No :	SMA1783H	Insured Vehicle No :	SDN9990L
Date of Loss:	01/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D204733C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA1783H	Engine No:	032013
Make & Model:	PORSCHE PANAMERA, 3.6 PDK (A)	Chassis No:	WP0ZZZ97ZJL181292
Reg. Date:	15/11/2018 (Man. Year: 2018)	Odometer:	28581 km
Colour:	White		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/45ZR19	Rear Tyre Size:	265/45ZR19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,283.75	4,243.79	3,039.96	41.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,520.00	4,010.00	3,510.00	46.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	14,803.75	8,253.79	6,549.96	44.25
+ GST 7.00/7.00% (\$\$)	1,036.26	577.77	458.49	44.24
Nett Amount (\$\$)	15,840.01	8,831.56	7,008.45	44.25

INSPECTION

Date of Assignment:	16/12/2020	
Date Inspected:	18/12/2020 Inspected At:	Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
		27A Tanjong Penjuru
		Singapore 609042
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2021)
Parts:	144	PORSCHE PANAMERA 3.6 PDK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA1783H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	2,198.80 FL	*2,198.80 FL
2	1		*FRONT BUMPER SPOILER	Deformed	677.50 FL	*677.50 FL
3	1		*FRONT GRILLE	Scratched	288.70 FL	*288.70 FL
4	1		*FRONT GRILLE LH	Serviceable	120.80 FL	*- FL
5	1		*FRONT GRILLE INSERT TRIM LH	Serviceable	97.60 FL	*- FL
6	1		*FRONT GRILLE SUPPORT DISC	Serviceable	92.80 FL	*- FL
7	1		*DISC BLACK MAT	Scratched	125.50 FL	*125.50 FL
8	1		*CAMERA HOUSING	Serviceable	42.20 FL	*- FL
9	1		*BRACKET FOR CAMERA	Serviceable	39.50 FL	*- FL
10	6		*SENSOR	Serviceable	1,485.00 FL	*- FL
11	6		*SENSOR GASKET	Necessary	18.60 FL	*18.60 FL
12	1		*NUMBER PLATE BRACKET	Cracked	83.50 FL	*83.50 FL
13	1		*FOAM PART LH	Necessary	55.50 FL	*55.50 FL
14	1		*FOAM PART RH	Necessary	55.50 FL	*55.50 FL
15	1		*FRONT BUMPER REINFORCEMENT	Serviceable	1,080.80 FL	*- FL
16	1		*FRONT BUMPER SPONGE	Serviceable	82.50 FL	*- FL
17	1		*SUPPORT LOWER REINFORCEMENT	Serviceable	303.20 FL	*- FL
18	1		*ADDITIONAL HEADLAMP LH	Scratched	744.10 FL	*744.10 FL
19	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
20	2		*ANTENNA	Necessary	445.40 FL	*445.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,087.50	4,713.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	803.75	469.31
Total Parts (\$\$)	7,283.75	4,243.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE/INSTALL FRONT BUMPER, LOWER SPOILER & ALL DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	3,900.00	1,560.00
2	TO RESPRAY FRONT BUMPER	New	1,850.00	1,300.00
3	TO SUPPLY FRONT LICENCE PLATE WITH CASING	New	70.00	70.00
4	TO TRANSFER THE FRONT BUMPER SENSORS	New	500.00	150.00
5	TO TRANSFER THE FRONT CAMERA	New	350.00	150.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	180.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
Gross Labour Cost (\$\$)			7,520.00	4,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >