

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20013899/APA3Q2
Date: 30/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070137967
Claimant Vehicle No :	GBD1545T	Insured Vehicle No :	GBE3315Y
Date of Loss:	04/12/2020	Nature of Claim:	TP
		Claim No:	5268181378SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD1545T		
Make & Model:	NISSAN NV200, 1.5 ABS AIRBAG 2WD 6DR EURO 5 (M)	Engine No:	K9KC400D053560
Reg. Date:	30/06/2014 (Man. Year: 2014)	Chassis No:	VSKYBAM20Z0080932
Colour:	Silver	Odometer:	161523 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,900.28	14,355.74	9,544.54	39.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	3,750.00	2,200.00	36.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,850.28	18,105.74	11,744.54	39.34
Approved Total (Overridden) (S\$)		14,500.00		

(S\$)	29,850.28	14,500.00	15,350.28	51.42
+ GST 7.00/7.00% (S\$)	2,089.52	1,015.00	1,074.52	51.42
Nett Amount (S\$)	31,939.80	15,515.00	16,424.80	51.42
+ Loss of Use (16.0 x S\$60.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		16,477.00		
Global Sum Settlement (S\$)		16,470.00		

INSPECTION

Date of Assignment: 15/12/2020

Date Inspected: 15/12/2020

Estimated Period of Repair: 14.0 days

Inspected At:

New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit
Singapore 417883**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$30,000.00(est) less LTA Rebate:\$14,470.00(est) = Nett Value :\$15,530.00(est)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT HEAD LAMP	Cracked	892.80 F	*892.80 FL
2	2		*FRONT HEAD LAMP TOP LID	Necessary	420.00 FS	*200.00 FS
3	2		*FRONT HEAD LAMP LOWER BRACKET	Not Necessary	151.40 F	*- FL
4	1		*FRONT BUMPER	Deformed	589.70 F	*589.70 FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	70.40 F	*70.40 FL
6	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
7	1		*FRONT BUMPER TOWING CAP	Not Necessary	120.20 F	*- FL
8	2		*FRONT BUMPER TOP SIDE COVER	Torn	724.40 F	*724.40 FL
9	1		*FRONT BUMPER TOP SIDE COVER STICKER	Necessary	80.00 FS	*30.00 FS
10	1		*FRONT BUMPER NUMBER PLATE	Cracked	50.00 FS	*25.00 FS
11	1		*SET FRONT BUMPER LOWER CENTRE GRILLE	Cracked	800.00 FS	*400.00 FS
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	614.90 F	*- FL
13	2		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	183.40 F	*- FL
14	1		*SET FRONT BUMPER LOWER SPOILER	Cracked	1,200.00 FS	*800.00 FS
15	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	297.80 F	*- FL
16	1		*SET FRONT GRILLE	Cracked	500.00 FS	*350.00 FS
17	8		*FRONT GRILLE CLIP	Necessary	52.00 F	*20.00 FL
18	1		*FRONT GRILLE EMBLEM LOGO	Necessary	73.50 F	*73.50 FL
19	1		*FRONT GRILLE LOWER MOULDING	Not Necessary	205.50 F	*- FL
20	2		*FRONT SUPPORT PANEL GARNISH	Torn	136.90 F	*136.90 FL
21	1		*REAR R/H BOOT LID	Distorted	960.90 F	*960.90 FL
22	2		*REAR R/H BOOT LID HINGE	Not Necessary	205.80 F	*- FL
23	1		*REAR R/H BOOT LID DCI LOGO	Necessary	56.20 F	*56.20 FL
24	1		*REAR R/H BOOT LID TOP LOCK	Not Necessary	261.00 F	*- FL
25	1		*REAR R/H BOOT LID LOWER LOCK	Damaged	290.60 F	*290.60 FL
26	1		*REAR R/H BOOT LID INNER RUBBER	Cut	96.40 F	*96.40 FL
27	1		*REAR R/H BOOT LID INNER TRIM BOARD	Deformed	152.50 F	*152.50 FL
28	8		*REAR R/H BOOT LID INNER TRIM BOARD CLIP	Necessary	52.00 F	*20.00 FL
29	1		*REAR L/H BOOT LID	Distorted	1,281.10 F	*1,281.10 FL
30	2		*REAR L/H BOOT LID HINGE	Bent	205.80 F	*205.80 FL
31	1		*REAR L/H BOOT LID EMBLEM LOGO	Necessary	155.10 F	*155.10 FL
32	1		*REAR L/H BOOT LID NV200 LOGO	Necessary	175.38 F	*175.38 FL
33	1		*REAR L/H BOOT LID CENTRE MOULDING	Deformed	336.00 F	*336.00 FL
34	1		*REAR L/H BOOT LID CENTRE MOULDING STICKER	Necessary	40.00 FS	*10.00 FS
35	1		*REAR L/H BOOT LID TOP LOCK	Not Necessary	261.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR L/H BOOT LID LOWER LOCK	Damaged	190.60 F	*190.60 FL
37	1		*REAR L/H BOOT LID INNER RUBBER	Cut	96.40 F	*96.40 FL
38	1		*REAR L/H BOOT LID INNER TRIM BOARD	Deformed	269.40 F	*269.40 FL
39	10		*REAR L/H BOOT LID INNER TRIM BOARD CLIP	Necessary	65.00 F	*20.00 FL
40	1		*REAR L/H BOOT LID STICKER	Necessary	40.00 F	*40.00 FL
41	2		*REAR TAIL LAMP	Cracked	517.40 F	*517.40 FL
42	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
43	1		*REAR BUMPER	Deformed	624.80 F	*624.80 FL
44	2		*REAR BUMPER SIDE RETAINER	Necessary	70.40 F	*70.40 FL
45	1		*REAR BUMPER SIDE REFLECTOR	N/S Cracked	73.00 F	*36.50 FL
46	1		*REAR BUMPER INNER FOAM	Cracked	133.80 F	*133.80 FL
47	1		*REAR BUMPER STICKER	Necessary	40.00 F	*40.00 FL
48	1		*SET REAR BUMPER SIDE EXHAUST ACCESSORIES	Deformed	400.00 FS	*250.00 FS
49	1		*REAR END PANEL OUTER	Distorted	386.20 F	*386.20 FL
50	1		*REAR END PANEL INNER	Distorted	850.80 F	*850.80 FL
51	1		*REAR END PANEL TOP MOULDING	Cracked	99.10 F	*99.10 FL
52	8		*REAR END PANEL TOP MOULDING CLIP	Necessary	52.00 F	*10.00 FL
53	1		*REAR END PANEL RUBBER	Cut	91.30 F	*91.30 FL
54	1		*REAR FLOOR PANEL	Distorted	2,848.00 F	*2,383.00 FL
55	1		*REAR SPARE TYRE BRACKET	Bent	252.00 F	*252.00 FL
56	1		*REAR EXHAUST	Bent	2,681.40 F	*545.00 FL
57	1		*REAR R/H BOOT LID WINDSCREEN SEAL	Necessary	50.00 FS	*40.00 FS
58	1		*REAR L/H BOOT LID WINDSCREEN SEAL	Necessary	50.00 FS	*40.00 FS
59	1		*REAR R/H BOOT LID 5 PAX STICKER	Necessary	20.00 FS	*10.00 FS
60	1		*REAR L/H BOOT LID 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
61	1		*REAR L/H BOOT LID NUMBER PLATE	Bent	50.00 FS	*30.00 FS
62	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
63	1		*REAR FLOOR PANEL CARPET	Not Necessary	650.00 FS	*- FS
64	1		*REAR FLOOR PANEL PLYWOOD	Cracked	450.00 FS	*300.00 FS
65	1		*REAR EXHAUST	Not Necessary	689.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,900.28	15,651.38
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,295.64
Total Parts (\$\$)	23,900.28	14,355.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION,CARPET & PLYWOOD	New	380.00	80.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	0.00
4	TO REMOVE & REFIT REAR L/H & R/H WINDSCREEN	New	240.00	160.00
5	GUM	New	100.00	100.00
6	TUFF KOTE	New	150.00	100.00
7	TO CHECK WIRING	New	100.00	60.00
8	PANEL BEATING	New	2,500.00	1,800.00
9	SPRAY PAINTING	New	2,000.00	1,400.00
Gross Labour Cost (\$\$)			5,950.00	3,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >