

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20013903/EVF3E2
Date: 14/01/2021

REFERENCE

Insured/Claimant: FOO MEI LIN ROSELINE MRS KONG MEI LIN ROSELINE Policy No: 1900157279
Date of Loss: 15/12/2020 Nature of Claim: OD Claim No: 4384174972SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP240K**
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UHX8994
Reg. Date: 06/09/2019 (Man. Year: 2019) Chassis No: MMBSTA13AKH002668
Colour: Silver Odometer: 28459 km
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$57,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 4,127.14 | 3,234.71 | 892.43 | 21.62 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 8,010.00 | 6,585.00 | 1,425.00 | 17.79 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,137.14 | 9,819.71 | 2,317.43 | 19.09 |
| - Excess (S\$) | 600.00 | 600.00 | 0.00 | 0.00 |
| (S\$) | 11,537.14 | 9,219.71 | 2,317.43 | 20.09 |
| + GST 7.00/7.00% (S\$) | 807.60 | 645.38 | 162.22 | 20.09 |
| Nett Amount (S\$) | 12,344.74 | 9,865.09 | 2,479.65 | 20.09 |

INSPECTION

Date of Assignment: 16/12/2020
Date Inspected: 16/12/2020 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------|---------------|------------|------------|
| 1 | 1 | | *FACE,RR BUMPER | Broken | 748.00 FL | *748.00 FL |
| 2 | 1 | | *BRACKET,RR BUMPER,LH | Broken | 28.00 FL | *28.00 FL |
| 3 | 1 | | *PANEL,TRUNK LID | Dented | 791.00 FL | *791.00 FL |
| 4 | 1 | | *HINGE,TRUNK LID,RH | Not Necessary | 203.00 FL | *- FL |
| 5 | 1 | | *HINGE,TRUNK LID,LH | Not Necessary | 203.00 FL | *- FL |
| 6 | 1 | | *WEATHERSTRIP,TRUNK LID | Crushed | 157.00 FL | *157.00 FL |
| 7 | 1 | | *LATCH,TRUNK LID | Not Necessary | 218.00 FL | *- FL |
| 8 | 1 | | *PANEL,QTR,OTR LH | Dented | 755.00 FL | *755.00 FL |
| 9 | 1 | | *PANEL,RR COMB LAMP HSG,LH | Dented | 60.00 FL | *60.00 FL |
| 10 | 1 | | *EXTN,QTR PANEL,UPR OTR LH | Dented | 118.00 FL | *118.00 FL |
| 11 | 1 | | *PANEL,RR END | Dented | 425.00 FL | *425.00 FL |
| 12 | 3 | | *SPACER,RR WINDOW | Necessary | 27.00 FL | *27.00 FL |
| 13 | 2 | | *STOPPER,WINDSHIELD GLASS | Necessary | 6.00 FL | *6.00 FL |
| 14 | 1 | | *MUD GUARD,RR LH | Necessary | 41.00 FL | *41.00 FL |
| 15 | 1 | | *SHIELD,RR WHEELHOUSE LH | Not Necessary | 40.00 FL | *- FL |
| 16 | 1 | | *GARNISH,RR END PANEL | Not Necessary | 336.00 FL | *- FL |
| 17 | 1 | | *MARK,THREE-DIA | Necessary | 69.00 FL | *69.00 FL |
| 18 | 1 | | *MARK,ATTRAGE | Necessary | 21.00 FL | *21.00 FL |
| 19 | 1 | | *TRIM,RR END | Not Necessary | 66.00 FL | *- FL |
| 20 | 1 | | *BOARD,TRUNK ROOM FLOOR | Broken | 195.00 FL | *195.00 FL |
| 21 | 1 | | *TRIM,TRUNK ROOM SIDE,LH | Crushed | 160.00 FL | *160.00 FL |
| 22 | 1 | | *LAMP ASSY,COMB,RR LH | Broken | 335.00 FL | *335.00 FL |
| 23 | 1 | | *REFLECTOR | Not Necessary | 23.00 FL | *- FL |
| 24 | 1 | | *BUZZER,KEYLESS OPERATIO,RR | Broken | 91.00 FL | *91.00 FL |
| 25 | 1 | | *ANT,KEYLESS OPERATION,RR | Broken | 96.00 FL | *96.00 FL |
| 26 | 1 | | *COVER,RR VENTILATOR | Not Necessary | 40.00 FL | *- FL |
| 27 | 1 | | *DUCT,RR VENTILATOR | Not Necessary | 30.00 FL | *- FL |
| 28 | 1 | | *SUNDRY | Necessary | 20.00 FS | *20.00 FS |
| 29 | 1 | | *C&C LOGO | Necessary | 40.00 FS | *40.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (S\$) | 5,342.00 | 4,183.00 |
| - List Item Discount on L Items 23.00/23.00% (S\$) | 1,214.86 | 948.29 |
| Total Parts (S\$) | 4,127.14 | 3,234.71 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|---------------------------------|-----------------|
| Labour Items | | | | |
| 1 | RENEW REAR BUMPER,BOOT LID,REAR FENDER LH,REAR LAMP HOUSING LH,REAR END PANEL | New | 3,600.00 | 2,700.00 |
| 2 | REMOVE & INSTALL REAR WINDSCREEN | New | 240.00 | 240.00 |
| 3 | REMOVE & INSTALL REAR COMARTMENT TRIMS & REAR FENDER TRIMS | New | 225.00 | 225.00 |
| 4 | SPRAY PAINT FOR REAR BUMPER,BOOTLID,REAR END PANEL,REAR FENDER LH,REAR LAMP HOUSING LH | New | 2,100.00 | 1,575.00 |
| 5 | APPLY SEALANT FOR REAR WINDSCREEN | New | 80.00 | 80.00 |
| 6 | APPLY SEALANT FOR ACCIDENT PORTION | New | 120.00 | 120.00 |
| 7 | CHECK WIRING & ELECTRICAL WIRING | New | 30.00 | 30.00 |
| 8 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New | 120.00 | 120.00 |
| 9 | REMOVE & INSTALL FUEL TANK SYSTEM | New | 225.00 | 225.00 |
| 10 | TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT | New | 120.00 | 120.00 |
| 11 | SPRAY PAINT FOR FRT BUMPER | New | 350.00 | 350.00 |
| 12 | REPAIR REAR COMPARTMENT (Supplementary) | New | 450.00 | 450.00 |
| 13 | SPRAY PAINT REAR COMPARTMENT (Supplementary) | New | 350.00 | 350.00 |
| | | | Gross Labour Cost (\$\$) | 8,010.00 |
| | | | | 6,585.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >