



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name KCV12020/F00 MEI LIN ROSELINE MRS.KONG M Reg No/Reg Date SMP240K*DC17P/ 06/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH002668 Engine No 3A92UHX8994 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	16/12/2020/ 10:35		442 / Cocolu	60765

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, BOOTLID, REAR FENDER LH, REAR LAMP HOUSING LH REAR END PANEL, 2	450 x 6			3600.00 2700
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN				240.00
E PNT88000 REMOVE & INSTALL REAR COMARTMENT TRIMS & REAR FENDER TRIMS				225.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR FENDER RH, REAR LAMP HOUSING RH,	350 x 4.5			2100.00 1575
M SUNDRY APPLY SEALANT FOR REAR WINDSCREEN				80.00
M SUNDRY C&C LOGO				40.00
M SUNDRY APPLY SEALANT FOR ACCIDNET PORTION				120.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
A 54900099 REMOVE & INSTALL FUEL TANK SYSTEM				225.00 (photo)
M SUNDRY Sundry				20.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER				350.00
M FACE,RR BUMPER	1.00	748.00	23.00	575.96
M BRACKET,RR BUMPER,LH	1.00	28.00	23.00	21.56
M PANEL,TRUNK LID	1.00	791.00	23.00	609.07
M HINGE,TRUNK LID,RH	1.00	203.00	23.00	156.31

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for a Mitsubishi Attrage.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Includes account details for LAX00000 and date 16/12/2020.

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts and their costs, including a large 'Estimate' watermark.

Handwritten notes: 'Stere CLKK) 19.30 on, 16/12/20', 'OO- AM Aul Excess - ? P/P By Pol spy 12 days'.

Summary table with 3 columns: Description, Amount, Total Payable. Shows a net total of 11,337.14 and a total payable of 12,130.74 including 7% GST.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.