

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20007296/KRS3Q2-1
Date: 07/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100419848
Claimant Vehicle No :	SKX4997R	Insured Vehicle No :	SJZ1437L
Date of Loss:	11/07/2020	Nature of Claim:	TP
		Claim No:	3744172397SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX4997R		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	L15B4024886
Reg. Date:	16/12/2015 (Man. Year: 2015)	Chassis No:	RU11104883
Colour:	Metallic Silver	Odometer:	95950 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Linglong 8 mm	Rear Left Side:	Linglong 8 mm
Front Right Side:	Linglong 8 mm	Rear Right Side:	Linglong 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,382.40	715.60	666.80	48.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	530.00	200.00	330.00	62.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,912.40	915.60	996.80	52.12
Approved Total (Overridden) (S\$)		700.00		

(S\$)	1,912.40	700.00	1,212.40	63.40
+ GST 7.00/7.00% (S\$)	133.87	49.00	84.87	63.40
Nett Amount (S\$)	2,046.27	749.00	1,297.27	63.40
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
(S\$)		929.00		
Liable Amount (50.00%) (S\$)		464.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		466.50		

INSPECTION

Date of Assignment: 14/07/2020

Date Inspected: 14/07/2020

Estimated Period of Repair: 2.0 days

Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL ARCH EXTENSION COVER RH	Dented / Bent	192.00 FL	*192.00 FL
2	1		*REAR ALLOY RIM RH	Dented	1,216.80 FS	*550.00 FS
3	1		*REAR SIDE BUMPER RH (NPA)	Repair	0.00 FL	*- FL
4	1		*REAR TYRE TUBE VALVE RH	Necessary	12.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,420.80	754.00
- List Item Discount on L Items 20.00/20.00% (S\$)	38.40	38.40
Total Parts (S\$)	1,382.40	715.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	250.00	80.00
2	LABOUR CHARGES TO REMOVE ,REFIX ,REPLACE REAR ALLOY RIM RH & ETC	New	80.00	20.00
3	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC	New	200.00	100.00
Gross Labour Cost (\$\$)			530.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >