

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013913/EQD3E2
Date: 02/02/2021

REFERENCE

Insured/Claimant: CHAN HEN FUI Policy No: 1900234418
Date of Loss: 14/12/2020 Nature of Claim: OD Claim No: 9317550590SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ1067H**
Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11AR9005
Reg. Date: 30/10/2019 (Man. Year: 2019) Chassis No: GF7W0601257
Colour: Brown Odometer: 9724 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$99,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm
Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,355.00	996.32	358.68	26.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	2,335.00	525.00	18.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,215.00	3,331.32	883.68	20.97
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	3,915.00	3,031.32	883.68	22.57
+ GST 7.00/7.00% (S\$)	274.05	212.19	61.86	22.57
Nett Amount (S\$)	4,189.05	3,243.51	945.54	22.57

INSPECTION

Date of Assignment: 16/12/2020
Date Inspected: 12/01/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*FACE, RR BUMPER	Dented	807.00 F	*807.00 FL
4	1		*BRKT, R/BMPR FACE SIDE, RH	Broken	12.00 F	*12.00 FL
5	1		*REINFORCEMENT, RR BUMPER, RH	Not Necessary	79.00 F	*- FL
6	1		*MOULDING, RR BUMPER, RH	Necessary	106.00 F	*106.00 FL
7	1		*MARK, OUTLANDER	Necessary	95.00 F	*95.00 FL
8	1		*DECAL, MIVEC (Supplementary)	Necessary	36.00 F	*36.00 FL
9	1		*MOULDING, RR WHEEL ARCH, RH (Supplementary)	Necessary	160.00 F	*160.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,355.00	1,276.00
- List Item Discount on L Items 0.00/23.00% (\$)	0.00	279.68
Total Parts (\$)	1,355.00	996.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER, REPAIR TAILGATE, REAR FENDER RH, SKID PLATE	New	900.00	900.00
2	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
3	SPRAY PAINT FOR REAR BUMPER, TAILGATE, REAR FENDER RH, SKID PLAT	New	1,750.00	1,225.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
			Gross Labour Cost (\$)	2,860.00
				2,335.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >