

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20013915/UBS3Q2

Date: 16/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLW8007R	Insured Vehicle No :	SHA4052Z
Date of Loss: 09/12/2020	Nature of Claim: TP	Claim No: MCT20120166

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW8007R		
Make & Model:	TOYOTA RUSH, 1.5 X (A)	Engine No:	3SZ2189397
Reg. Date:	22/01/2009 (Man. Year: 2008)	Chassis No:	J200E0023972
Colour:	Black	Odometer:	145146 km
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,588.50	1,219.65	368.85	23.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	660.00	40.00	5.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,288.50	1,879.65	408.85	17.87
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	2,288.50	1,500.00	788.50	34.45
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
Nett Liability (S\$)		1,680.00		

INSPECTION

Date of Assignment:	16/12/2020	
Date Inspected:	16/12/2020 Inspected At:	Soc Leon Motor Works (Kaki Bukit) 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2021)
Parts:	M1-SUV	TOYOTA RUSH 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW8007R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WITH FOGLIGHT COVER)	Distorted / Torn	1,180.00 FL	*981.10 FL
2	1		*BUMPER SIDE RETAINER (RH)	Not Necessary	198.00 FL	*- FL
3	1		*SET BUMPER CLIPS	Necessary	60.00 FL	*50.00 FL
4	1		*BUMPER REINFORCEMENT	Dented	680.00 FL	*595.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,118.00	1,626.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	529.50	406.55
Total Parts (\$\$)	1,588.50	1,219.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR KNOCKING & REPLACING PARTS	New	300.00	280.00
2	SPRAYPAINTING	New	400.00	380.00
Gross Labour Cost (\$\$)			700.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >