

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG20013919/APS3Q2

Date:

14/06/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2070119309

Claimant Vehicle No : SMQ8866Y**Insured Vehicle No :**

SMU4176K

Date of Loss: 13/12/2020

Nature of Claim:

TP

Claim No:

6883774979SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMQ8866Y**

Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)

Engine No: CVK087333

Reg. Date: 27/09/2019 (Man. Year: 2019)

Chassis No:

WAUZZZF57KA074742

Colour: Red

Odometer:

7110 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size:

245/40 R18

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,170.00	9,183.84	5,986.16	39.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,252.00	2,822.00	3,430.00	54.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,422.00	12,005.84	9,416.16	43.96
+ GST 7.00/7.00% (S\$)	1,499.54	840.41	659.13	43.96

Nett Amount (S\$)	22,921.54	12,846.25	10,075.29	43.96
		+ Loss of Use (4.0 x S\$100.00/day) (S\$)	400.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	13,248.25	

INSPECTION

Date of Assignment: 18/12/2020

Date Inspected: 18/12/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	402.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	225.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE -LH	Not Necessary	62.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Not Necessary	468.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	36.00 FS	*- FS
8	1		*FRONT PARKING AID SENSOR -OUTER	Not Necessary	242.00 FS	*- FS
9	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
10	1		*FRONT FENDER -LH	Dented	1,048.00 FS	*838.40 FS
11	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	53.00 FS	*- FS
12	1		*FRONT FENDER CLOSING ELEMENT -LH	Not Necessary	73.00 FS	*- FS
13	1		*FRONT FENDER BRACKET -LH	Not Necessary	35.00 FS	*- FS
14	1		*FRONT FENDER BRACE -LH	Bent	117.00 FS	*93.60 FS
15	1		*DEFORMATION ELEMENT BRACKET -LH	Not Necessary	49.00 FS	*- FS
16	1		*FRONT FENDER TRIM -LH	Necessary	157.00 FS	*125.60 FS
17	1		*WHEEL HOUSING LINER -LH	Not Necessary	272.00 FS	*- FS
18	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	167.00 FS	*- FS
19	1		*WHEEL SPOILER -LH	Damaged	73.00 FS	*57.76 FS
20	1		*WHEEL SPOILER TRIM -LH	Not Necessary	35.00 FS	*- FS
21	1		*STONE CHIP GUARD -LH	Not Necessary	50.00 FS	*- FS
22	1		*TOP FENDER LEDGE COVER -UPPER	Not Necessary	35.00 FS	*- FS
23	1		*TOP FENDER LEDGE COVER -LOWER	Not Necessary	16.00 FS	*- FS
24	1		*LED HEADLIGHT -LH	Cut	7,812.00 FS	*6,249.60 FS
25	1		*LIFT CYLINDER -LH	Not Necessary	196.00 FS	*- FS
26	1		*FRONT ALUMINIUM RIM -LH	Not Necessary	1,012.00 FS	*- FS
27	1		*SUNDRIES	Necessary	200.00 FS	*18.08 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **15,170.00** **9,183.84**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT ,RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,500.00	1,100.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,252.00	2,822.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >