

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO20013920/GUvf3e2	
	50 RAFFLES PLAC TOWER SINGAPO		Date:	29/12/2020		
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMA 928Y	Veh. Inspected	ł	SMR 5138E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2003664/THE	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		16/12/2020	
2.	Vehicle Particulars & Condition					
	Make & Model	HONDA FIT 1.3G	c.c		1317	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	GK33428947	Colour		GREY	
	Odometer	6361 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/55 R16	FALKEN		9 mm	
	L/H Front Tyre	195/55 R16	FALKEN		9 mm	
	R/H Rear Tyre	195/55 R16	FALKEN		9 mm	
	L/H Rear Tyre	195/55 R16	FALKEN		9 mm	
4.	Description of Damages					
	THE VEHICLE SUS PORTION.	CLE SUSTAINED DAMAGES AT THE FRONT AND REAR				
5.	General Information					
	Accident Date	13/12/2020	Inspect Date /	Time	16/12/2020 (04:15 PM)	
	Survey held at BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875					
5a.	. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000					
5b. Estimate Days of Repair						
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				

Report Ref No. CS3/SMO20013920/GUvf3e2

Inspected By

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser