

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20013926/ETD3E2

Date: 09/03/2021

REFERENCE

Insured/Claimant: SHANMUGAVEL RAJAN RAJA JAWAHAR
Date of Loss: 13/12/2020

Policy No: 1800016443
Nature of Claim: OD Claim No: 6636806450SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFE3383C	Engine No:	4J11XK6125
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0401054
Reg. Date:	28/02/2018 (Man. Year: 2017)	Odometer:	52223 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$85,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,524.00	1,934.22	3,589.78	64.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,900.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,424.00	3,834.22	3,589.78	48.35
+ GST 7.00/7.00% (S\$)	519.68	268.40	251.28	48.35
Nett Amount (S\$)	7,943.68	4,102.62	3,841.06	48.35

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 14/12/2020 Inspected At:

Estimated Period of Repair: 4.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FENDER, FR RH	Dented	688.00 F	*688.00 FL
3	1		*SHAFT AS, FR AXLE DRIVE, RH	Not Necessary	1,285.00 F	*- FL
4	1		*WHEEL, SPARE TIRE DISC	Cut	1,102.00 F	*1,102.00 FL
5	1		*ARM ASSY, FR SUSP, LWR RH	Not Necessary	323.00 F	*- FL
6	1		*STRUT, FR SUSP, RH	Bent	465.00 F	*465.00 FL
7	1		*BEARING, FR SUSP STRUT	Necessary	32.00 F	*32.00 FL
8	1		*LINK, FR SUSP STABILIZER	Not Necessary	137.00 F	*- FL
9	1		*GEAR & LINK ASSY, STEERING	Not Necessary	1,211.00 F	*- FL
10	1		*END ASSY, TIE ROD	Not Necessary	62.00 F	*- FL
11	1		*MOULDING, FR WHEEL ARCH, RH (Supplementary)	Cut	199.00 F	*199.00 FL
					Sub Total (\$)	5,524.00 2,506.00
					- List Item Discount on L Items 0.00/23.00% (\$)	0.00 571.78
					Total Parts (\$)	5,524.00 1,934.22

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR FRT BUMPER, RENEW FRT FENDER RH	New	450.00	450.00
2	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
3	TRANSFER FRT RIGHT RIM	New	30.00	30.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	RENEW FRT UNDER CARRIAGE	New	450.00	450.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH	New	700.00	700.00
Gross Labour Cost (\$\$)			1,900.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >