

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013932/AGS3Q2
Date: 18/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000004069
Claimant Vehicle No :	SJF9324G	Insured Vehicle No :	SMR5521G
Date of Loss:	14/12/2020	Nature of Claim:	TP
		Claim No:	7725264447SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF9324G		
Make & Model:	HONDA STREAM, 1.8 X (A)	Engine No:	R18A1771033
Reg. Date:	16/06/2008 (Man. Year: 2008)	Chassis No:	RN61063814
Colour:	Black	Odometer:	155049 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,234.96	2,559.92	6,675.04	72.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	980.00	3,220.00	76.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,434.96	3,539.92	9,895.04	73.65
Approved Total (Overridden) (S\$)		2,800.00		

Nett Amount (S\$)	13,434.96	2,800.00	10,634.96	79.16
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		2,700.00		
Nett Liability (S\$)		5,987.45		

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 16/12/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Ishare Auto Pte. Ltd. (HQ)
8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT
Singapore 415875

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	688.90 FL	*- FL
2	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	19.20 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Not Necessary	58.80 FL	*- FL
4	2		*REAR FENDER INNER TRIM	Not Necessary	594.00 FL	*- FL
5	2		*TAILLAMP	Not Necessary	795.20 FL	*- FL
6	4		*TAILLAMP BOLT COVER	Not Necessary	50.80 FL	*- FL
7	1		*TAILGATE	Dented	1,093.20 FL	*903.00 FL
8	1		*TAILGATE LOGO	Necessary	41.90 FL	*41.90 FL
9	1		*TAILGATE EMBLEM STREAM	Necessary	31.60 FL	*31.60 FL
10	1		*TAILGATE THIRD BRAKE LAMP	Not Necessary	263.70 FL	*- FL
11	1		*TAILGATE OUTER GARNISH	Deformed	184.30 FL	*184.30 FL
12	1		*TAILGATE OUTER LOCK HANDLE	Not Necessary	84.20 FL	*- FL
13	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	75.60 FL	*- FL
14	1		*TAILGATE INNER LOCK	Damaged	159.80 FL	*159.80 FL
15	1		*TAILGATE WEATHERSTRIP	Not Necessary	171.60 FL	*- FL
16	2		*TAILGATE STOPPER	Not Necessary	48.00 FL	*- FL
17	1		*TAILGATE WIPER BLADE	Not Necessary	87.40 FL	*- FL
18	1		*TAILGATE WIPER MOTOR	Not Necessary	695.90 FL	*- FL
19	1		*TAILGATE WIPER ARM	Not Necessary	169.70 FL	*- FL
20	1		*TAILGATE WIPER BOLT COVER	Not Necessary	32.20 FL	*- FL
21	1		*TAILGATE INNER HANDLE	Not Necessary	29.00 FL	*- FL
22	1		*TAILGATE INNER BOARD	Cracked	369.70 FL	*285.00 FL
23	1		*TAILGATE WINDSCREEN	Cut	980.00 FL	*980.00 FL
24	1		*TAILGATE WINDSCREEN MOULDING	Necessary	164.30 FL	*164.30 FL
25	1		*REAR END PANEL	Repair	396.70 FL	*- FL
26	1		*REAR END PANEL TOP GARNISH	Not Necessary	116.70 FL	*- FL
27	2		*REAR FLOOR PANEL COVER BOARD	Not Necessary	253.00 FL	*- FL
28	1		*REAR FLOOR PANEL COVER BOARD (INNER SUPPORT)	Not Necessary	697.60 FL	*- FL
29	1		*REAR TOOLS SPONGE	Not Necessary	168.20 FL	*- FL
30	1		*REAR JACK COVER GARNISH	Not Necessary	185.00 FL	*- FL
31	1		*REAR NUMBER PLATE	Bent	80.00 FS	*50.00 FS
32	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
33	1		*SET TAILLAMP CLIP	Not Necessary	40.00 FS	*- FS
34	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
35	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
36	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	80.00 FS	*20.00 FS	
37	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS	
38	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS	
39	1		*TAILGATE WINDSCREEN SOLAR FILM	Necessary	550.00 FS	*200.00 FS	
40	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS	
41	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	40.00 FS	*- FS	
42	1		*SET REAR JACK COVER GARNISH CLIP	Not Necessary	60.00 FS	*- FS	
43	1		*JACK	Not Necessary	150.00 FS	*- FS	
44	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS	
45	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS	
					Sub Total (\$)	10,976.20	3,109.90
					- List Item Discount on L Items 20.00/20.00% (\$)	1,741.24	549.98
					Total Parts (\$)	9,234.96	2,559.92

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,400.00	300.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	400.00
3	TUFF COAT	New	250.00	30.00
4	WIRING AND BULB CHECK	New	180.00	0.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	0.00
6	REMOVE AND REFIX REVERSE CAMERA AID DISTANCE SETTING	New	80.00	50.00
7	REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	TRANFER TAILGATE MECHANISM	New	80.00	80.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
10	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
11	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
			Gross Labour Cost (S\$)	4,200.00
				980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >