

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013944/QPS3Q2
Date: 08/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070101144
Claimant Vehicle No :	SLF2976Y	Insured Vehicle No :	GBK3730A
Date of Loss:	15/12/2020	Nature of Claim:	TP
		Claim No:	9228476182SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF2976Y		
Make & Model:	TOYOTA SIENTA, 1.5 G (A)	Engine No:	2NR8570170
Reg. Date:	22/08/2016 (Man. Year: 2015)	Chassis No:	NSP1707017543
Colour:	Silver	Odometer:	307862 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,724.72	5,093.70	1,631.02	24.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	2,350.00	920.00	28.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,994.72	7,443.70	2,551.02	25.52
Approved Total (Overridden) (S\$)		5,950.00		

(S\$)	9,994.72	5,950.00	4,044.72	40.47
+ GST 7.00/7.00% (S\$)	699.63	416.50	283.13	40.47
Nett Amount (S\$)	10,694.35	6,366.50	4,327.85	40.47
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		6,838.50		
Global Sum Settlement (S\$)		6,800.00		

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 16/12/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Lion City Rentals Pte Ltd (HQ)
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*F/L DOOR	Dented	1,404.00 FL	*1,233.90 FL
2	1		*F/L DOOR REGULATOR	Bent	480.50 FL	*380.00 FL
3	1		*F/L DOOR WINDOW MOTOR	Jammed	528.30 FL	*420.00 FL
4	1		*R/L DOOR	Dented	1,404.00 FL	*1,279.00 FL
5	1		*R/L FENDER	Dented	1,255.00 FL	*980.00 FL
6	1		*R/L FENDER RUBBER PAD	Scratched	280.00 FL	*150.00 FL
7	1		*R/L DOOR RUBBER PAD	Scratched	390.00 FL	*280.00 FL
8	1		*REAR BUMPER	Crumpled	1,257.83 FL	*788.70 FL
9	1		*SET BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
10	1		*BODY SEALANT	Necessary	300.00 FS	*60.00 FS
11	1		*LH DOOR BOTTOM HINGE	Serviceable	120.00 FL	*- FL
12	1		*LH DOOR UPPER HINGE	Serviceable	180.00 FL	*- FL
13	1		*LH SIDE MIRROR COVER	Cracked	180.00 FL	*180.00 FL
14	1		*LH SIDE MIRROR ASSY	Crumpled	980.00 FL	*980.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,839.63	6,761.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,114.91	1,667.90
Total Parts (\$\$)	6,724.72	5,093.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING F/L DOOR ,R/L DOOR ,REAR BUMPER OUT TO FACILITATE REPLACEMENT OF PARTS ,ALSO REPAIR R/L FENDER	New	1,200.00	1,200.00
2	TO RESPRAY REAR BUMPER ,F/L DOOR ,R/K DOOR AND R/L FENDER	New	1,200.00	1,000.00
3	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	120.00	0.00
4	TRANSFER TAILGATE MECHANISM	New	100.00	100.00
5	TO CONFIGURE KEYLESS NETWORK SECURITY SYSTEM BACK TO FACTORY SPEFICATION	New	300.00	0.00
6	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS	New	300.00	0.00
7	TOWING FEE	New	50.00	50.00
Gross Labour Cost (S\$)			3,270.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >