

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20013948/UGS3Q2
Date: 25/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800089226
Claimant Vehicle No :	SLC6953C	Insured Vehicle No :	SDY1113Y
Date of Loss:	15/12/2020	Nature of Claim:	TP
		Claim No:	9950439671SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC6953C	Engine No:	3ZRB714341
Make & Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Chassis No:	ZSU600070362
Reg. Date:	23/05/2016 (Man. Year: 2015)	Odometer:	87397 km
Colour:	Silver		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,050.20	5,491.90	8,558.30	60.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	2,020.00	1,300.00	39.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,370.20	7,511.90	9,858.30	56.75
Approved Total (Overridden) (S\$)		6,000.00		

(S\$)	17,370.20	6,000.00	11,370.20	65.46
Nett Amount (S\$)	18,586.11	6,420.00	12,166.11	65.46
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,902.00		

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 16/12/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Repair	1,655.20 F	*- FL
2	1		*REAR DOOR O/S	Badly Dented	1,645.20 F	*1,381.10 FL
3	1		*REAR DOOR OUTER CHROME MOULDING LOWER O/S	Scratched / Cracked	655.10 F	*381.10 FL
4	1		*REAR DOOR GLASS OUTER CHROME MOULDING O/S	Necessary	422.50 F	*199.50 FL
5	1		*REAR DOOR GLASS REGULATOR & MOTOR O/S	Shorted / Jammed	845.20 F	*499.50 FL
6	2		*REAR DOOR HINGE O/S	Twisted	250.00 F	*250.00 FL
7	1		*REAR DOOR CHECKER O/S	Serviceable	188.00 F	*- FL
8	1		*REAR DOOR INNER LOCK O/S	Not Necessary	566.20 F	*- FL
9	1		*REAR DOOR INNER RUBBER O/S	Necessary	311.20 F	*188.20 FL
10	1		*REAR DOOR FRAME BLACK GARNISH O/S	Necessary	281.50 F	*211.50 FL
11	1		*SET REAR DOOR FRAME BLACK OUTER STICKER O/S	Necessary	80.00 F	*80.00 FL
12	1		*SET REAR DOOR FRAME BLACK INNER STICKER O/S	Necessary	80.00 F	*80.00 FL
13	1		*REAR DOOR INNER TRIM BOARD O/S	Deformed / Cracked	1,022.30 F	*645.20 FL
14	1		*SET REAR DOOR INNER TRIM BOARD CLIPS O/S	Necessary	50.00 F	*50.00 FL
15	1		*REAR STEP INNER TOP GARNISH O/S	Twisted	233.50 F	*182.60 FL
16	1		*ROCKER PANEL O/S	Badly Dented	866.90 F	*845.10 FL
17	1		*ROCKER PANEL GARNISH O/S	Deformed	845.50 F	*655.20 FL
18	1		*SET ROCKER PANEL GARNISH CLIPS O/S	Necessary	50.00 F	*50.00 FL
19	1		*REAR FENDER O/S	Repair	1,099.20 F	*- FL
20	1		*REAR WHEEL HUB BEARING O/S	Damaged	680.50 F	*450.20 FL
21	1		*REAR LOWER ARM O/S	Serviceable	622.20 F	*- FL
22	1		*REAR SPORT RIM O/S 18 INCH	Cut	1,600.00 FS	*880.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,050.20	7,029.20
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,537.30
Total Parts (S\$)	14,050.20	5,491.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	0.00
3	TO DISMANTLE & REFIX CUSHION UPHOLTERY	New	120.00	80.00
4	TO DISMANTLE & REFIX REAR UNDER CARRIAGE	New	150.00	100.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
6	TO TRANSFER REAR DOOR MECHANISM	New	100.00	60.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	800.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (S\$)			3,320.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >