#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG20013952/ATF3E2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 03/06/2021

**REFERENCE** 

Insured/Claimant: YANG XIAO Policy No: 1900097924

Date of Loss: 13/12/2020 Nature of Claim: OD Claim No: 5815710413SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SML2722U

Make & Model: AUDI Q2, 1.4 (A) Engine No: CHZC29865

Reg. Date: 13/05/2019 (Man. Year: 2019) Chassis No: WAUZZZGA3KA054581

Colour: White Odometer: 16145 km

Engine Capacity: 999 cc
Market Value/New Car Price: \$\$105,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		18,474.00	8,090.24	10,383.76	56.21
Miscellaneous Items		0.00	0.00	0.00	
Labour		11,792.00	5,382.00	6,410.00	54.36
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	30,266.00	13,472.24	16,793.76	55.49
	- Excess (S\$)	3,400.00	3,400.00	0.00	0.00
	(S\$)	26,866.00	10,072.24	16,793.76	62.51
	+ GST 7.00/7.00% (S\$)	1,880.62	705.06	1,175.56	62.51
	Nett Amount (S\$)	28,746.62	10,777.30	17,969.32	62.51

**INSPECTION** 

Date of Assignment: 16/12/2020

Date Inspected: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

## **Recommended Parts**

	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	1,854.00 FS	*- FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	343.00 FS	*- FS
3	1	*FRONT BUMPER ADAPTER - LH	Not Necessary	35.00 FS	*- FS
4	1	*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	167.00 FS	*- FS
5	1	*FRONT BUMPER END CAP - LH	Not Necessary	34.00 FS	*- FS
6	1	*HEADLIGHT MOUNTING - LH	Not Necessary	117.00 FS	*-FS
7	1	*LED HEADLIGHT - LH	Not Necessary	4,859.00 FS	*-FS
8	1	*LIFT CYLINDER - LH	Not Necessary	141.00 FS	*-FS
9	1	*FRONT FENDER - LH	Dented	1,134.00 FS	*907.20 FS
10	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	40.00 FS	*-FS
11	1	*FRONT FENDER BRACKET - OUTER	Not Necessary	16.00 FS	*- FS
12	1	*FRONT FENDER BRACKET - CENTRE	Not Necessary	47.00 FS	*- FS
13	1	*FRONT FENDER BRACKET - INNER	Not Necessary	16.00 FS	*- FS
14	1	*FRONT FENDER BRACE - LH	Not Necessary	37.00 FS	*- FS
15	1	*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	33.00 FS	*- FS
16	1	*WHEEL HOUSING LINER - LH	Not Necessary	194.00 FS	*- FS
17	1	*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	57.00 FS	*- FS
18	2	*FRONT WHEEL COVER - LH / RH	N/S Cut / O/S Necessary	636.00 FS	*508.80 FS
19	1	*FRONT DOOR - LH	Dented	2,499.00 FS	*1,999.20 FS
20	1	*FRONT DOOR ATTACHMENT PARTS	Not Necessary	93.00 FS	*- FS
21	1	*FRONT DOOR CATCH	Damaged	119.00 FS	*94.80 FS
22	1	*FRONT DOOR COVER - LH	Necessary	254.00 FS	*202.80 FS
23	1	*EXTERIOR MIRROR MOUNTING - LH	Cracked	1,013.00 FS	*810.40 FS
24	1	*MIRROR CAP - LH	Cracked	167.00 FS	*133.20 FS
25	1	*MIRROR GLASS - LH	Shattered	217.00 FS	*173.20 FS
26	1	*FRONT ALUMINIUM RIM - LH	Cut	568.00 FS	*454.40 FS
 27	1	*SUNDRIES	Necessary	200.00 FS	*30.24 FS
28	1	*FRONT DOOR WINDOW-LH	Cut	195.00 FS	*155.60 FS
_0	•	(Supplementary)	Out	100.001 0	100.001 0
29	1	*FRONT DOOR WINDOW APERTUNE SEAL -LH OUTER	Cut	134.00 FS	*106.80 FS
		(Supplementary)			
30	1	*REAR WHEEL COVER-LH	Cut	168.00 FS	*134.40 FS
31	1	(Supplementary) *REAR DOOR - LH	Dented	2,499.00 FS	*1 000 20 ES
31	ı	(Supplementary)	Dented	2,499.00 F3	1,999.20 F3
32	1	*REAR DOOR OUTER SEAL - LH	Necessary	134.00 FS	*106.80 FS
		(Supplementary)	,		
33	1	*BONDING AGENT	Not Necessary	47.00 FS	*- FS
		(Supplementary)	N. (N.	05.00.50	* 50
34	1	*CLEANING SOLUTION (Supplementary)	Not Necessary	65.00 FS	*-FS
35	1	*REAR DOOR CATCH-LH	Damaged	119.00 FS	*94.80 FS
00	'	(Supplementary)	Damaged	113.0013	∂ <del>+</del> .001°3
36	1	*REAR DOOR COVER-LH (Supplementary)	Necessary	223.00 FS	*178.40 FS
F=Fra	nchise	part. S=SpcNett.		P	
		•	Total Parts (S\$)		8,090.24

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,500.00
5	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER	New	4,500.00	1,800.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT ALIGNMENT	New	280.00	280.00
7	TO TOW VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI - SYSTEM MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES. (Supplementary)	New	280.00	280.00
10	TO INSTALL SOLAR FLIM FOR LHS FRONT DOOR FOR LHS FRONT DOOR WINDOW GLASS (Supplementary)	New	400.00	0.00
11	TO REW LHS REAR DOOR (Supplementary)	New	800.00	500.00
12	TO RESPRAY LHS REAR DOOR (Supplementary)	New	900.00	550.00
	Gross Labour	Cost (S\$)	11,792.00	5,382.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >