

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20013955/T1QD3E2

Date: 29/03/2021

REFERENCE

Insured/Claimant: CHONG SIN NAM TRADING Policy No: DMCVSNW00056492001

Date of Loss: 09/12/2020

Nature of Claim: OD

Claim No: SNM20D204794/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY3227D	Engine No:	1KD2732433
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y90K208532
Reg. Date:	04/08/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,107.22	34,926.88	-819.66	-2.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,969.00	3,082.80	886.20	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	38,076.22	38,009.68	66.54	0.17
Approved Total (Overridden) (\$\$)		30,400.00		
- Excess (\$\$)	0.00	500.00	-500.00	
(\$\$)	38,076.22	29,900.00	8,176.22	21.47
+ GST 7.00/7.00% (\$\$)	2,665.34	2,093.00	572.34	21.47
Nett Amount (\$\$)	40,741.56	31,993.00	8,748.56	21.47

INSPECTION

Date of Assignment:	16/12/2020	Present Location:	Goldbell Engineering Pte Ltd (Tuas)
Date Inspected:	17/12/2020	Inspected At:	Goldbell Engineering Pte Ltd (Tuas) 10 Tuas Ave 18 Singapore 638894
Estimated Period of Repair:	18.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Mar 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GY3227D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		34,107.22 F	*34,926.88 F
F=Franchise part.						
Total Parts (S\$)					34,107.22	34,926.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL OF LABOUR	New	3,423.00	2,692.20
2	TOTAL PAINT INCLUDING MATERIAL	New	546.00	390.60
Gross Labour Cost (S\$)			3,969.00	3,082.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >