

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 22 Dec 2020

**Preliminary Advice**

Vehicle No	: GY3227D	Accident Date	: 09/12/2020
Make	: TOYOTA DYNA 150	Policy No.	: DMCVSNW00056492001
Assignment Date	: 16/12/2020	Excess	: S\$500.00
Date of Inspection	: 17/12/2020	Est. Duration of Repair	: 18
Inspection At	: GOLDBELL ENGINEERING PTE LTD (TUAS) 10 TUAS AVE 18 SINGAPORE 638894		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,076.22
Revised Amount	:S\$	29,579.16
Check Items (Estimated)	:S\$	8,462.86
Total	:S\$	38,042.02

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	54,000.00
COE / PARF Rebate	:S\$	18,571.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,429.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : REPAIRER ABLE TO REPAIR THE VEHICLE WITHIN \$35,000.00 ON LUMP SUM BASIS.