

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013957/GGS3Q2
Date: 10/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900020520
Claimant Vehicle No :	SMN7093H	Insured Vehicle No :	SMJ2183K
Date of Loss:	10/12/2020	Nature of Claim:	TP
		Claim No:	4040712452SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN7093H		
Make & Model:	ADIVA AD1 200, 190cc 3W	Engine No:	L13B3935181
Reg. Date:	26/08/2019 (Man. Year: 2019)	Chassis No:	GK33420690
Colour:	Blue	Odometer:	22319 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,539.94	2,680.58	1,859.36	40.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	1,430.00	1,680.00	54.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,649.94	4,110.58	3,539.36	46.27
+ GST 7.00/7.00% (S\$)	535.50	287.74	247.76	46.27

Nett Amount (S\$)	8,185.44	4,398.32	3,787.12	46.27
+ Loss of Use (1.0 x S\$60.00/day) (S\$)		60.00		
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,888.32		
Global Sum Settlement (S\$)		4,880.00		

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 18/12/2020

Estimated Period of Repair: 5.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Ubi)
 320 UBI ROAD 3
 Singapore 408649

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Buckled	976.80 FL	*850.60 FL
2	1		*REAR TAILGATE RUBBER	Not Necessary	110.76 FL	*- FL
3	1		*REAR TAILGATE LOCK	Bent	224.52 FL	*131.80 FL
4	1		*REAR TAIL GATE GARNISH	Not Necessary	202.20 FL	*- FL
5	1		*REAR EMBLEM	Not Necessary	18.84 FL	*- FL
6	1		*FIT WORDING	Necessary	42.00 FL	*35.00 FL
7	1		*REAR TAIL LAMP RH	Scratched	317.40 FL	*363.00 FL
8	1		*REAR TAIL LAMP LH	Scratched	317.40 FL	*317.40 FL
9	1		*REAR BUMPER	Deformed	832.20 FL	*710.30 FL
10	1		*REAR BUMPER REINFORCEMENT	Not Necessary	500.00 FL	*- FL
11	1		*REAR BUMPER SPONGE	Not Necessary	200.00 FL	*- FL
12	1		*REAR BUMPER GARNISH LH	Not Necessary	25.80 FL	*- FL
13	1		*REAR BUMPER GARNISH CENTER	Not Necessary	72.60 FL	*- FL
14	1		*REAR BUMPER GARNISH RH	Not Necessary	27.95 FL	*- FL
15	1		*REAR END PANEL	Buckled	416.00 FL	*378.40 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	79.04 FL	*79.04 FL
17	15		*REAR BUMPER CLIPS	Necessary	52.50 FL	*23.40 FL
18	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	21.97 FL	*- FL
19	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	21.97 FL	*- FL
20	1		*REAR BUMPER LOWER GARNISH	Not Necessary	250.00 FL	*- FL
21	1		*REAR CAMERA	Not Necessary	200.00 FS	*- FS
22	1		*REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
23	1		*REAR WINDSCREEN RUBBER	Necessary	124.28 FL	*124.28 FL
24	1		*REAR NUMBER PLATE	Scratched	45.00 FS	*45.00 FS
25	1		*REAR SPARE TYRE TOP COVER	Not Necessary	253.20 FL	*- FL
26	1		*INNER SEAL	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,557.43	3,283.22
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,017.49	602.64
Total Parts (\$\$)	4,539.94	2,680.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKET ETC ,REMOVE AND REINSTALL DAMAGE PARTS TEST AND RECTIFY FOR PROPER FUNCTIONING	New	100.00	30.00
2	REMOVE & REINSTALL REAR WINDSCREEN	New	180.00	100.00
3	TO REMOVE AND REINSTALL /REAR BUMPER SENSOR	New	120.00	40.00
4	TO DISMANTLE AND TRANSFER TAIL GATE FITTING AND MECHANISM TO NEW TAIL GATE /FACILITATE REPAIR	New	300.00	60.00
5	CUT & WELD REAR END PANEL /KNOCK AND REPAIR SPARE TYRE PANEL ,REAR BOTH FENDER AND AFFECTED AREA	New	860.00	600.00
6	PUTTY & SPRAY PAINT REAR TAIL GATE ,REAR BUMPER ,END PANEL ,SPARE TYRE PANEL ,BOTH FENDER AND AFFECTED AREA	New	1,550.00	600.00
Gross Labour Cost (S\$)			3,110.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >