

320 UBI ROAD 3 SINGAPORE 408649 **ACCIDENT REPAIR ESTIMATES**

Our Ref:			
Type of Claim :	TP	Vehicle No.	: SMN7093H
		Make & Model	: HONDA FIT
		Year of Manufacture	: 2019
		Chassis No.	: GK33420690
Ins Company :	AIG	Engine No.	: L13B3935181
Excess :		Policy No.	•
Date of Accident :10	/12/2020	Time of Accident	: 08.30
Suggested Days of Repair:		In-house Vehicle Asse	ssor
Repair Estimates		Case Owner	:
		Signature	:
Parts (a) Cost / List Price Items	\$ 5,087.00	Contact No	
Plus/Less15%	\$ 763.05	68485725/26 - JOHAR	I / TINIF
Total of Cost / List	\$ 4,323.95	00 100 120 120 100 111 111	
(b) Nett Price Items	\$ -		
Less	***************************************		
Total of Nett Item			
(c) Special Nett Items	\$ 510.00		
Total Parts Cost (Appendix A)	\$ 4,833.95		
Labour (Appendix B)	\$ 3,110.00		
Total Repair Cost	\$ 7,943.95		
The above total will be subjected t	o 7% G.S.T.		
		A MANAGEMENT	
Name of Surveyor			
Company			
Survey conducted on	•	at	
Remarks By Surveyor			
(a) The repair of this vehicle is	authorized / is not aut	horized until further notice	
(b) Recommended Days of Re	pair :	day(s)	
(c) Resurvey	: Required / No	ot Required	
(d) Excess	:\$		
(e) Signature of surveyor	:	Date:	

320 UBI ROAD 3 SINGAPORE 408649 TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No	: SMN7093H	Case Owner: JOHARI

Make & Model : HONDA FIT 1.3 GF CVT Year Manufac: 2019

Chassis No : **GK33420690** Engine No : **L13B395181**

Sales Order : ____ Supplier : ____

Order By : _____ Type of Claim: <u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR TAIL GATE	1		\$ 976.80	11100	O/IX	our veyor
2	REAR TAILGATE RUBBER	1		\$ 110.76	· · · · · · · · · · · · · · · · · · ·		
3	REAR TAIL GATE LOCK	1		\$ 224.52	14100000		
4	REAR TAIL GATE GARNISH	1		\$ 202.20			
5	REAR EAMBLEM	1		\$ 18.84			
6	FIT WORDING	1		\$ 42.00			
7	REAR TAIL LAMP RH	1		\$ 317.40			
8	REAR TAIL LAMP LH	1	**********	\$ 317.40			
9	REAR BUMPER	1		\$ 832.20			
10	REAR BUMPER REINFORCEMENT	1		\$ 500.00			
11	REAR BUMPER SPONGE	1		\$ 200.00			
12	REAR BUMPER GARNISH LH	1		\$ 25.80			
13	REAR BUMPER GARNISH CENTER	1		\$ 72.60			
14	REAR BUMPER GARNISH RH	1		\$ 27.95			
15	REAR END PANEL	1		\$ 416.00			
16	REAR END PANEL TOP GARNISH	1		\$ 79.04			
17	REAR BUMPER CLIP'S	15		\$ 52.50			
18	REAR BUMPER SIDE RETAINER LH	1		\$ 21.97			
19 I	REAR BUMPER SIDE RETAINER RH	1		\$ 21.97			
20 I	REAR BUMPER LOWER GARNISH	1		\$ 250.00			
21 F	REAR CAMERA	1				\$ 200.00	
22 F	REVERSE SENSOR	1				\$ 200.00	
23 F	REAR WIND SCREEN RUBBER	1		\$ 124.28			
24 F	REAR NUMBER PLATE	1				\$ 45.00	
25 F	REAR SPARE TYRE TOP COVER	1		\$ 253.20			
26	NNER 25050	1				\$ 25.00	10:11 AM

Spark Car Care ComfortDelGro Engineering Pte Ltd

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649 Tel: 68438723/68438736 FAX: 67436072

<u>Labour</u>

Vehicle No.	:	SMN7093H	Case Owner	:	JOHARI	
Make & Model	:	HONDA FIT	Year of Manufacture	:	2019	

rear of Manufacture :					
Labour Description	Esimated Price	Adjusted Price			
TO DISCONNECT AND CHECK ELECTRICAL WIRING , WIRE SOCKET	\$100.00				
ETC ,REMOVE AND REINSTALL DAMAGE PARTS TEST AND RECTIFY					
FOR PROPER FUNCTIONING .					
REMOVE & REINSTALL REAR WINDSCREEN	\$180.00				
TO REMOVE AND REINSTALL / REAR BUMPER SENSOR	\$120.00	100000000000000000000000000000000000			
TO DISMANTLE AND TRANSFER TAIL GATE FITTING AND	\$300.00	. 1-8-11-21			
MECHANISM TO NEW TAIL GATE / FACILITATE REPAIR.		1000000			
	\$860.00	**************************************			
TYRE PANEL, REAR BOTH FENDER AND AFFECTED AREA.		19300-1			
PUTTY & SPRAY PAINT REAR TAIL GATE ,REAR BUMPER , END	\$1,550.00				
PANEL , SPARE TYERV PANEL , BOTH FENDER AND AFFECTED					
AREA.	***************************************				

		· · · · · · · · · · · · · · · · · · ·			
		Miles and a second of			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKET ETC, REMOVE AND REINSTALL DAMAGE PARTS TEST AND RECTIFY FOR PROPER FUNCTIONING. REMOVE & REINSTALL REAR WINDSCREEN TO REMOVE AND REINSTALL / REAR BUMPER SENSOR TO DISMANTLE AND TRANSFER TAIL GATE FITTING AND MECHANISM TO NEW TAIL GATE / FACILITATE REPAIR. CUT & WELD REAR END PANEL / KNOCK AND REAPIR SPARE TYRE PANEL, REAR BOTH FENDER AND AFFECTED AREA. PUTTY & SPRAY PAINT REAR TAIL GATE , REAR BUMPER, END	TO DISCONNECT AND CHECK ELECTRICAL WIRING , WIRE SOCKET TO DISCONNECT AND CHECK ELECTRICAL WIRING , WIRE SOCKET ETC , REMOVE AND REINSTALL DAMAGE PARTS TEST AND RECTIFY FOR PROPER FUNCTIONING . REMOVE & REINSTALL REAR WINDSCREEN TO REMOVE AND REINSTALL / REAR BUMPER SENSOR \$120.00 TO DISMANTLE AND TRANSFER TAIL GATE FITTING AND MECHANISM TO NEW TAIL GATE / FACILITATE REPAIR. CUT & WELD REAR END PANEL / KNOCK AND REAPIR SPARE TYRE PANEL, REAR BOTH FENDER AND AFFECTED AREA. PUTTY & SPRAY PAINT REAR TAIL GATE , REAR BUMPER , END PANEL , SPARE TYERV PANEL , BOTH FENDER AND AFFECTED			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.