Our Ref:



ComfortDelGro Engineering

## 320 UBI ROAD 3 SINGAPORE 408649 ACCIDENT REPAIR ESTIMATES

| Type of Claim ;  | TP   | Vehicle No.   | SMN7093H   |
|--|--|---|--|
|  |  | Make & Model  | HONDA FIT  |
|  |  | Year of Manufacture   | 2019   |
|  |  | Chassis No.   | GK33420690   |
| Ins Company :  | AIG  | Engine No.  | L13B3935181  |
| Excess :   |  | Policy No.  | :  |
| Date of Accident :10   | /12/2020   | Time of Accident  | : 08.30  |
| Suggested Days of Repair :   |  | In-house Vehicle Asse   | ssor   |
| Repair Estimates   |  | Case Owner  | :  |
| Parts (a) Cost / List Price Items Plus/Less 15% Total of Cost / List (b) Nett Price Items Less Total of Nett Item (c) Special Nett Items Total Parts Cost (Appendix A) Labour (Appendix B) | \$ 5,087.00<br>\$ 763.05<br>\$ 4,323.95<br>\$ -<br>\$ 510.00<br>\$ 4,833.95<br>\$ 3,110.00 | To resurvey be To display dar Parts prices a Third party su No illegal mod Supplementar | of the following: efore/after spray painting maged part(s) during resurvey re subject to confirmation rvey is on a "Without Prejudice" basis lification(s) is allowed y item(s) must be resurveyed and nal approval from Insurance Company |
| Total Repair Cost  | \$ 7,943.95  |   |  |
| The above total will be subjected  | to 7% G.S.T.   |   |  |
| Name of Surveyor   | : <u>G</u> u   | io Qianf  | 82880282   |

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair

(c) Resurvey

(d) Excess

Surveyor

And Mark Mark Company

Required Not Required

Mod Require

Date:

(e) Signature of surveyor

## Spark Car Care

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649 TEL:68438723/68438736 Fax:67436072

| SMN7093H |  |
|----------|--|
|----------|--|

Case Owner : **JOHARI** 

Model

: HONDA FIT 1.3 GF CVT

assis No

Year Manufac: 2019

: GK33420690

Engine No

: L13B395181

Sales Order

Supplier

Order By

Type of Claim: TP

| S/No | . art Description                                | QTY             | Cost<br>Price |    | List<br>Price | Nett<br>Price |    |        | Disposition By<br>Surveyor |
|------|--|-----------------|---------------|----|---------------|---------------|----|--------|----------------------------|
| 1_   | REAR TAIL GATE                                   | 1               |               | \$ | 976.80        |               |    | 0/14   | Surveyor                   |
| 2    | REAR TAILGATE RUBBER                             | 1               |               | \$ | 110.76        |               |    |        |                            |
| 3    | REAR TAIL GATE LOCK ?                            | 1               |               | \$ | 224.52        |               |    |        |                            |
| 4    | REAR TAIL GATE GARNISH スパル                       | 1               |               | \$ | 202.20        |               | +  |        |                            |
| 5    | REAR EAMBLEM $\times$ $\mathcal{N}\mathcal{N}$ . | 1               |               | \$ | 18.84         |               | +  |        |                            |
| 6    | FIT WORDING / WC.                                | 1               |               | \$ | 42.00         |               | +- |        |                            |
| 7    | REAR TAIL LAMP RH ?                              | 1               |               | \$ | 317.40        |               | +  |        |                            |
| 8    | REAR TAIL LAMP LH 7                              | 1               |               | \$ | 317.40        |               | +  |        |                            |
| 9    | REAR BUMPER / 🕊                                  | 1               |               | \$ | 832.20        |               |    |        |                            |
| 10   | REAR BUMPER REINFORCEMENT ?                      | 1               |               | \$ | 500.00        |               |    |        |                            |
| 11   | REAR BUMPER SPONGE                               | 1               |               | \$ | 200.00        |               |    |        |                            |
| 12   | REAR BUMPER GARNISH LH                           | 1               |               | \$ | 25.80         |               |    |        |                            |
| 13   | REAR BUMPER GARNISH CENTER X                     | <sub>2</sub> 1/ | W.            | \$ | 72.60         |               |    |        |                            |
| 14   | REAR BUMPER GARNISH RH 🗶                         | / 1             |               | \$ | 27.95         |               |    |        |                            |
| 15   | REAR END PANEL ?                                 | 1               |               | \$ | 416.00        |               |    |        |                            |
| 16   | REAR END PANEL TOP GARNISH $\diagup$ $\&$        | <b>L</b> 1      |               | \$ | 79.04         |               |    |        |                            |
| 17   | REAR BUMPER CLIP'S / MC                          | 15              |               | \$ | 52.50         |               |    |        |                            |
| 18   | REAR BUMPER SIDE RETAINER LH                     | 1               |               | \$ | 21.97         |               |    |        |                            |
| 19   | REAR BUMPER SIDE RETAINER RH                     | 1               |               | \$ | 21.97         |               | _  |        |                            |
| 20   | REAR BUMPER LOWER GARNISH                        | 1               |               | \$ | 250.00        |               | _  |        |                            |
| 21   | REAR CAMERA 🗡 🖊 🗸 .                              | 1               |               | _  |               |               | \$ | 200.00 |                            |
| 22   | REVERSE SENSOR 7                                 | 1               |               |    |               |               | \$ | 200.00 |                            |
| 23   | REAR WIND SCREEN RUBBER /                        | - 1             |               | \$ | 124.28        |               | +  |        |                            |
| - 1  | REAR NUMBER PLATE / Suft                         | 1               |               |    |               |               | \$ | 45.00  |                            |
| 25   | REAR SPARE TYRE TOP COVER MM                     | $V_1$           |               | \$ | 253.20        |               | +  |        |                            |
|      | INNERSEASO / MU.                                 | 1               |               |    |               |               | \$ | 25.00  | 10:11 /                    |

## Spark Car Care ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649 Tel: 68438723/68438736 FAX: 67436072

| se No.      | : | SMN7093H  | Case Owner          | : | JOHARI |
|-------------|---|-----------|---------------------|---|--------|
| ske & Model | : | HONDA FIT | Year of Manufacture | : | 2019   |

| ARE      | * MODE : HONDA FIT Year of Manufacture                  | 2019              |                   |  |
|----------|---|-------------------|-------------------|--|
| /No      | Labour Description                                      | Esimated<br>Price | Adjusted<br>Price |  |
|          |   |                   |                   |  |
| 1        | TO DISCONNECT AND CHECK ELECTRICAL WIRING , WIRE SOCKET | \$100.00          | 1                 |  |
|          | ETC ,REMOVE AND REINSTALL DAMAGE PARTS TEST AND RECTIFY |                   |                   |  |
|          | FOR PROPER FUNCTIONING .                                |                   |                   |  |
| 2        | REMOVE & REINSTALL REAR WINDSCREEN                      | \$180.00          | 100               |  |
| 3        | TO REMOVE AND REINSTALL / REAR BUMPER SENSOR            | \$120.00          | 40                |  |
| 4        | TO DISMANTLE AND TRANSFER TAIL GATE FITTING AND         | \$300.00          | 60                |  |
|          | MECHANISM TO NEW TAIL GATE / FACILITATE REPAIR.         |                   |                   |  |
| 5        | CUT & WELD REAR END PANEL / KNOCK AND REAPIR SPARE      | \$860.00          | 400               |  |
|          | TYRE PANEL, REAR BOTH FENDER AND AFFECTED AREA.         |                   |                   |  |
| 6        | PUTTY & SPRAY PAINT REAR TAIL GATE ,REAR BUMPER , END   | \$1,550.00        | Y00.              |  |
|          | PANEL , SPARE TYERV PANEL , BOTH FENDER AND AFFECTED    |                   |                   |  |
|          | AREA.   |                   |                   |  |
|          |   |                   |                   |  |
| -        |   |                   |                   |  |
|          |   |                   |                   |  |
|          |   |                   | h po              |  |
| $\dashv$ |   |                   |                   |  |
|          |   |                   |                   |  |
|          |   |                   |                   |  |
| -        |   |                   |                   |  |
|          |   |                   |                   |  |
| _        |   |                   |                   |  |
|          |   | affected areas    | Λην               |  |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.