LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013958/R1QD3E2

24/12/2020 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle

SMK2265C **Insured Vehicle No: SME284S** No:

12/12/2020 Nature of Claim: TP Claim No: 1470052959SG Date of Loss:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK2265C

Make & Model: TOYOTA COROLLA, 1.5 (A) Engine No: 1ZR0B68627

Reg. Date: 29/06/2018 (Man. Year: 2018) Chassis No: MR053REH604583505

Colour: Odometer: 46040 km

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/12/2020

16/12/2020 Inspected At: 1 BUKIT BATOK CRESCENT, #04-56 WCEGA PLAZA Date Inspected:

Singapore 658064

Car Laboratories Pte Ltd (HQ)

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

/ Part No.	o. Particulars	Condition	Repairer's	Amount
	*REAR BUMPER	Deformed	0.00 F	*-F
	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
	*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
	*REAR END PANEL	Bent	0.00 F	*- F
	*REAR LH TAILLAMP	Scratched	0.00 F	*- F
	*REAR RH TAILLAMP	Scratched	0.00 F	*- F
	*BOOTLID	Bent	0.00 F	*- F
	*BOOTLID EMBLEM	Necessary	0.00 F	*- F
	*BOOTLID LOCK	Bent	0.00 F	*- F
	*BOOTLID RUBBER	Necessary	0.00 F	*- F
	*SPARE TYRE PANEL	Repair	0.00 F	*- F
	*BOOTLID LATCH COVER	Cracked	0.00 F	*- F
	*BOOTLID LATCH	Bent	0.00 F	*- F
	*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
se part.				
		Total Parts (S\$)	0.00	0.00
se par	t.		t.	t

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >