

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013970/BQF3E2

Date: 28/12/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800006833		
Claimant Vehicle No :	SJH1576M	Insured Vehicle No :	SLJ9063P		
Date of Loss:	12/12/2020	Nature of Claim:	TP	Claim No:	1958272376SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH1576M	Engine No:	R18A1771876
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61064651
Reg. Date:	28/07/2008 (Man. Year: 2008)	Odometer:	120803 km
Colour:	Brown		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Good Rich 5 mm	Rear Left Side:	Good Rich 5 mm
Front Right Side:	Good Rich 5 mm	Rear Right Side:	Good Rich 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	16/12/2020	Merlin Motor & Engineering Works (HQ)
Date Inspected:	17/12/2020 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #03-13 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
3	2		*REVERSE SENSOR	Short Circuit	0.00 F	*- F
4	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*- F
5	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F
6	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F
7	1		*TAILGATE	Dented	0.00 F	*- F
8	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE GARNISH	Broken	0.00 F	*- F
10	1		*TAILGATE WIPER MOTOR	Not Damaged	0.00 F	*- F
11	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
					Total Parts (\$\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >