

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013983/R1QD3E2

Date: 24/12/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800050265		
Claimant Vehicle No :	FBM4817S	Insured Vehicle No :	GBH3570K		
Date of Loss:	12/12/2020	Nature of Claim:	TP	Claim No:	3920234447SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM4817S		
Make & Model:	DUCATI SCRAMBLER SIXTY2, 399cc	Engine No:	ML0800A2E004834
Reg. Date:	16/11/2017 (Man. Year: 2017)	Chassis No:	ZDMKC02AAJB004503
Colour:	Black	Odometer:	36332 km
Engine Capacity:	803 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80 R18	Rear Tyre Size:	110/80 R18
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	16/12/2020		
Date Inspected:	16/12/2020	Inspected At:	Race Werks Pte Ltd (HQ) Block 1008 Bukit Merah Lane 3, #01-26 Singapore 159722
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WING MIRROR LH	Scratched	0.00 F	*- F
2	1		*HANDLE BAR BALANCER LH	Bent	0.00 F	*- F
3	1		*CLUTCH LEVER	Broken	0.00 F	*- F
4	1		*CENTER FAIRING COVER (09) LH	Scratched	0.00 F	*- F
5	1		*RADIATOR COWLING	Scratched	0.00 F	*- F
6	1		*CLUTCH ENGINE COVER	Scratched	0.00 F	*- F
7	1		*FOOT GEAR SHIFTER	Scratched	0.00 F	*- F
8	1		*REAR SUB FRAME	Repair	0.00 F	*- F
9	1		*REAR NUMBER PLATE	Cracked	0.00 F	*- F
10	1		*SLIDER CENTRE	Scratched	0.00 F	*- F
11	1		*SLIDER REAR LH	Scratched	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >