

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20013989/QQD3Q2

Date: 31/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900164450

Claimant
Vehicle No : SBS6875D **Insured Vehicle No :** SKK3108R

Date of Loss: 11/12/2020 Nature of Claim: TP Claim No: 1736253048SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS6875D		
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 D (A)	Engine No:	902926C1085011
Reg. Date:	05/05/2015 (Man. Year: 2014)	Chassis No:	WEB62808323128575
Colour:	Multi-colour	Odometer:	449686 km
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	700.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	700.00	700.00	0.00	0.00
+ GST 7.00/7.00% (\$\$)	49.00	49.00	0.00	0.00
Nett Amount (\$\$)	749.00	749.00	0.00	0.00

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 16/12/2020

Inspected At:

SBS Transit Ltd (YCK)
3 Yio Chu Kang Crescent
Singapore 786010

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE RIGHT SIDE HEADLAMP COVER }	New	700.00	700.00
2	REPAIR RIGHT SIDE PANEL NO.1 }	New	0.00	0.00
3	REPAIR RIGHT SIDE BATTERY DOOR }	New	0.00	0.00
4	REPAIR 1PC X FRONT BUMPER BRACKET }	New	0.00	0.00
5	SPRAY PAINTING RIGHT SIDE HEADLAMP COVER }	New	0.00	0.00
Gross Labour Cost (\$\$)			700.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >