

CS/MSG 20013990/573 ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bar. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBG 9168E Yr Regn: Nov / 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hisson Cabstar c.c 2953

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 48590 T/Radio: Insured / Std / NI / NA

Eng/No: ZD30026610H

C/No: JHISC2F24Z0860380

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 185 / 75 R15

R: 155 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: Koyote Rear: Dunlop.

R/Bal. 5 mm R/Bal. 5/8 mm

L/Bal. 5 mm L/Bal. 5/8 mm

D.O.A. 15/12/2022 D.O.A. 18/12/2022

Survey held at JWG AMIC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MSG SLH 5687U

21/12/2022 JWG 215 2500 - with 5 days of rev (Red 23,542.74, 90%)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2) 29/12/20-Typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S+RS SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format: Merimen

Lump Sum H.B.T. (\$ 2500)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	16/12/2020 17:26 (SGT)
Date of Accident	15/12/2020 18:10 (SGT)
Exact Location of Accident	71 Woodlands Ave 3, #01-01 Marsiling MRT Station, Singapore 739044
Additional Location Information	WOODLANDS AVENUE 3 (BESIDE MARSILING MRT)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG9168E
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	G. COOL ENGINEERING PTE LTD
Company Reg No	201533140K
Email Address	kevinlau7569@gmail.com
Mobile Phone No	(Phone) +65-98243952
Alternative Phone No	+65-98243952

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Cabstar
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Goods vehicle

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	20-MT108982-R02
Cover Note Number	-

DRIVER

Name of Driver	DEWAN MD HASAN
Passport No/FIN	G8113393Q
Date Of Birth	25/12/1983

Occupation	Outdoor
Date Of Driving Pass	09/08/2019
Driving experience	1 YEAR AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-86720321
Alt. Phone Number	-
Email Address	kevinlau7569@gmail.com
Address	WOODLANDS INDUSTRIAL PARK E1
Address complement	BLOCK 4 LEVEL 3
Postcode	757727
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	AFTER RAIN
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	WONG IU SING
Gender	Male

PASSENGER 2

Name	SHEIKH SOHAG
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

AS PER ATTACHED SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN5687U
Vehicle Manufacturer	Toyota
Vehicle Model	Prius

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLD6682D
Vehicle Manufacturer	Mercedes
Vehicle Model	C200k
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: MSIG INSURANCE (SINGAPORE) PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SLN5687U [YOUR INSURED] & GBG9168E [OUR CLIENT]
ON 15/12/2020.

ESTIMATED REPAIR COSTS FOR GBG9168E

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	REAR TAILGATE <i>key</i>	\$ 2,179.00	X
3PCS	REAR TAILGATE HINGE @ \$102.70 EACH <i>key</i>	\$ 308.10	X
2PCS	REAR TAILGATE LOCK LH / RH @ \$217.31 EACH <i>SLC</i>	\$ 434.62	X
2PCS	REAR TAILGATE LOCK BRACKET LH / RH @ \$107.20 EACH <i>SLC</i>	\$ 214.40	X
2PCS	REAR TAILGATE STOPPER LH / RH @ \$71.78 EACH <i>SLC</i>	\$ 143.56	X
2PCS	REAR TAILGATE STOPPER BRACKET LH / RH @ \$132.09 EACH <i>HH</i>	\$ 264.18	X
2PCS	REAR SIDE GATE LH / RH @ \$1,954.72 EACH <i>HH</i>	\$ 3,909.44	X
2PCS	TAIL LAMP LH / RH @ \$453.70 EACH <i>N/S CRK / 1st O/S HH (266.30)</i>	\$ 907.40	LL
2PCS	TAIL LAMP BRACKET LH / RH @ \$135.82 EACH <i>N/S 3rd O/S HH</i>	\$ 271.64	LL
1PC	REAR END PANEL <i>Denbu</i> <i>458-W</i>	\$ 1,074.59	LL
1PC	REAR FLOOR PANEL <i>HH</i>	\$ 2,880.90	X
2PCS	CHASSIS BRACKET @ \$314.52 EACH <i>HH</i>	\$ 629.04	X
1PC	REAR NO. PLATE LAMP <i>HH</i>	\$ 107.20	X
1PC	SPARE TYRE BRACKET <i>HH</i>	\$ 498.56	X
1PC	SPARE TYRE BOLT <i>HH</i>	\$ 310.80	X
1PC	SPARE TYRE HOLDER <i>HH</i>	\$ 541.92	X
1PC	REAR EXHAUST PIPE <i>HH</i>	\$ 1,345.29	X
1PC	REAR EXHAUST MOUNTING <i>HH</i>	\$ 182.40	X

860.12
774.10

PARTS SUM: \$ 16,203.04
PARTS LESS 10%: \$ 1,620.30
PARTS TOTAL: \$ 14,582.74

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE <i>HH</i>	\$ 100.00	X
*	TO SUPPLY FLOOR PANEL SEALANT <i>HH</i>	\$ 80.00	X
*	TO SUPPLY REAR END PANEL SEALANT <i>HH</i>	\$ 80.00	40%
*	TO SUPPLY 70KM STICKER <i>HH</i>	\$ 50.00	20%
*	TO SUPPLY TAILGATE CHECKERED PLATE <i>HH</i>	\$ 1,000.00	X

*	TO SUPPLY TAILGATE 6 PAX STICKER <i>hec</i>	\$ 50.00	20/-
*	TO SUPPLY TAILGATE ADVERTISEMENT STICKER <i>hec</i>	\$ 1,500.00	300/-
*	TO SUPPLY REVERSE CAMERA <i>Dam / shorted</i>	\$ 600.00	400/-
*	TO SUPPLY REVERSE SENSOR <i>Dam / broken</i> <i>1000.00</i>	\$ 300.00	220/-
*	TO RNR REAR METAL DECK TO FACILITATE REPAIRS	\$ 1,800.00	40/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,400.00	700/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,400.00	500/-
*	TO RNR REVERSE SENSOR TO FACILITATE REPAIRS	\$ 200.00	30/-
*	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	\$ 200.00	50/-
*	TO TUFF COAT DAMAGED AREAS <i>1350.00</i>	\$ 300.00	40/-
*	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	\$ 150.00	30/-
*	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 250.00	40/-

LABOUR & S/N TOTAL: \$ 11,460.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 26,042.74

18/12/2020 @ 1100h

N/A Antenna

2/5km

5 days.

Wan

LKK Auto

8

Check P&A prices

3124.10

4/5 2500/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: