

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20013990/DVF3Q2

Date: 31/12/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

Claimant
Vehicle No : GBG9168E

Insured Vehicle No : SLN5687U

Date of Loss: 15/12/2020

Nature of Claim: TP

Claim No: 632084

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG9168E**

Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD
EURO 5 (A)

Engine No: ZD30026610N

Reg. Date: 30/11/2017 (Man. Year: 2017)

Chassis No: JN1SC2F24Z0860380

Colour: Silver

Odometer: 48590 km

Engine Capacity: 2953 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/75R15

Rear Tyre Size: 155R13 (D)

Front Left Side: Koyote 5 mm

Rear Left Side: Dunlop 5/5 mm

Front Right Side: Koyote 5 mm

Rear Right Side: Dunlop 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,342.74	1,774.11	16,568.63	90.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,700.00	1,350.00	6,350.00	82.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,042.74	3,124.11	22,918.63	88.00
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	26,042.74	2,500.00	23,542.74	90.40
+ GST 7.00/7.00% (S\$)	1,822.99	175.00	1,647.99	90.40
Nett Amount (S\$)	27,865.73	2,675.00	25,190.73	90.40

INSPECTION

Date of Assignment: 17/12/2020

Date Inspected: 18/12/2020 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Dec 2020)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG9168E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	2,179.00 FL	*- FL
2	3		*REAR TAILGATE HINGE	Repair	308.10 FL	*- FL
3	2		*REAR TAILGATE LOCK LH/RH	Serviceable	434.62 FL	*- FL
4	2		*REAR TAILGATE LOCK BRACKET LH/RH	Serviceable	214.40 FL	*- FL
5	2		*REAR TAILGATE STOPPER LH/RH	Serviceable	143.56 FL	*- FL
6	2		*REAR TAILGATE STOPPER BRACKET LH/RH	Not Necessary	264.18 FL	*- FL
7	1		*TAIL LAMP LH/RH	N/s Cracked/O/s Not Necessary	907.40 FL	*266.30 FL
8	1		*TAIL LAMP BRACKET LH/RH	N/s Bent/O/s Not Necessary	271.64 FL	*135.82 FL
9	1		*REAR END PANEL	Dented	1,074.59 FL	*458.00 FL
10	1		*REAR FLOOR PANEL	Not Necessary	2,880.90 FL	*- FL
11	2		*CHASSIS BRACKET	Not Necessary	629.04 FL	*- FL
12	1		*REAR NO PLATE LAMP	Not Necessary	107.20 FL	*- FL
13	1		*SPARE TYRE BRACKET	Not Necessary	498.56 FL	*- FL
14	1		*SPARE TYRE BOLT	Not Necessary	310.80 FL	*- FL
15	1		*SPARE TYRE HOLDER	Not Necessary	541.92 FL	*- FL
16	1		*REAR EXHAUST PIPE	Not Necessary	1,345.29 FL	*- FL
17	1		*REAR EXHAUST MOUNTING	Not Necessary	182.40 FL	*- FL
18	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
19	1		*FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
20	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
21	1		*70KM STICKER	Necessary	50.00 FS	*20.00 FS
22	1		*TAILGATE CHECKERED PLATE	Not Necessary	1,000.00 FS	*- FS
23	1		*TAILGATE 6PAX STICKER	Necessary	50.00 FS	*20.00 FS
24	1		*TAILGATE ADVERTISEMENT STICKER	Necessary	1,500.00 FS	*300.00 FS
25	1		*REVERSE CAMERA	Damaged/Shorted	600.00 FS	*400.00 FS
26	1		*REVERSE SENSOR	Damaged/Broken	300.00 FS	*220.00 FS
27	2		*REAR SIDE GATE LH/RH	Not Necessary	3,909.44 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 19,963.04 1,860.12
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,620.30 86.01

Total Parts (\$\$) 18,342.74 1,774.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR REAR METAL DECK TO FACILITATE REPAIRS	New	1,800.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	500.00
4	TO RNR REVERSE SENSOR TO FACILITATE REPAIRS	New	200.00	30.00
5	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	New	200.00	50.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
7	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	150.00	30.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
Gross Labour Cost (S\$)			7,700.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >