

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20013993/KTF3Q2

**Date:** 14/01/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00004272000
<b>Claimant Vehicle No :</b>	SGN414H	<b>Insured Vehicle No :</b>	SLE2518S
Date of Loss:	09/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D204882/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGN414H	Engine No:	1ZZ2686118
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100324173
Reg. Date:	03/11/2006 (Man. Year: 2006)	Odometer:	224484 km
Colour:	Metallic Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,852.80	2,980.70	4,872.10	62.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	1,300.00	2,430.00	65.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,582.80</b>	<b>4,280.70</b>	<b>7,302.10</b>	<b>63.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>(S\$)</b>	11,582.80	3,400.00	8,182.80	70.65
<b>+ GST 7.00/7.00% (S\$)</b>	810.80	238.00	572.80	70.65
<b>Nett Amount (S\$)</b>	<b>12,393.60</b>	<b>3,638.00</b>	<b>8,755.60</b>	<b>70.65</b>

### INSPECTION

Date of Assignment:	16/12/2020	
Date Inspected:	17/12/2020 Inspected At:	Bodyfix (HQ) 10 Ang Mo Kio Industrial Park 2, #04-06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2021)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGN414H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,362.00 F	*1,277.00 FL
2	1		*TAILGATE LOGO	Necessary	70.80 F	*70.80 FL
3	1		*TAILGATE CHROME HANDLE	Serviceable	341.00 F	*- FL
4	2		*TAILGATE HINGES	Repair	364.00 F	*- FL
5	1		*TAILGATE WEATHERSTRIP	Serviceable	319.00 F	*- FL
6	1		*TAILGATE INNER TRIM BOARD	Serviceable	302.00 F	*- FL
7	1		*TAILGATE LOCK	Dented	417.00 F	*417.00 FL
8	1		*EMBLEM WISH	Necessary	121.00 F	*76.80 FL
9	1		*REAR WINDSCREEN	Cracked	1,102.00 F	*1,102.00 FL
10	1		*SET REAR WINDSCREEN MOULDING	Necessary	155.00 F	*155.00 FL
11	1		*REAR BUMPER	Buckled	514.00 F	*514.00 FL
12	10		*REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
13	2		*REAR BUMPER SIDE RETAINER	Serviceable	182.00 F	*- FL
14	2		*REAR BUMPER REFLECTOR	Serviceable	160.00 F	*- FL
15	1		*REAR END PANEL	Repair	440.00 F	*- FL
16	1		*REAR END PANEL TOP GARNISH	Serviceable	253.00 F	*- FL
17	2		*REAR TAIL LAMP	Serviceable	742.00 F	*- FL
18	1		*REAR WIPER MOTOR	Serviceable	479.00 F	*- FL
19	1		*REAR WIPER BLADE	Serviceable	89.00 F	*- FL
20	1		*REAR NUMBER PLATE	Bent	45.00 FS	*45.00 FS
21	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
22	1		*SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,852.80</b>	<b>3,892.60</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	911.90
<b>Total Parts (\$\$)</b>	<b>7,852.80</b>	<b>2,980.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS	New	80.00	30.00
2	TO CHECK & TEST LIGHTING FUNCTIONS & REVERSE SENSOR WIRING	New	100.00	50.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	150.00	120.00
4	LABOUR TO REPLACE ABOVE PARTS,PANEL BEAT,REPAIR & RE-ALIGN DAMAGE PARTS	New	1,800.00	500.00
5	SPRAY PAINT TAILGATE (INNER & OUTER),REAR BUMPER,REAR END PANEL & OTHER AFFECTED AREAS	New	1,600.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>3,730.00</b>	<b>1,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >