

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20013994/GTD3E2  
**Date:** 14/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900008752  
**Claimant Vehicle No** : SKC231D **Insured Vehicle No :** SMH6398S  
Date of Loss: 15/12/2020 Nature of Claim: TP Claim No: 3047437737SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC231D**  
Make & Model: VOLKSWAGEN NEW GOLF, 1.4 AT 5K13G5 (A) Engine No: CAX799761  
Reg. Date: 15/07/2011 (Man. Year: 2011) Chassis No: WVVZZZ1KZBW315825  
Colour: Black Odometer: 175436 km  
Engine Capacity: 1390 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 16/12/2020  
Date Inspected: 16/12/2020 Inspected At: Garage 13 Pte. Ltd. (HQ)  
8 Kaki Bukit Avenue 4, #03-46 Premier  
Singapore 415875  
Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Cut	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Cut	0.00 F	*- F
3	2		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*- F
4	1		*REAR BUMPER	Deformed	0.00 F	*- F
5	1		*REAR BUMPER LOWER	Broken	0.00 F	*- F
6	1		*REAR BUMPER BRACKET	Cracked	0.00 F	*- F
7	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
8	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
9	1		*REAR END PANEL	Repair	0.00 F	*- F
10	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
11	1		*TAILGATE	Bent	0.00 F	*- F
12	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
13	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
14	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
15	1		*TAILGATE LOCK	Cut	0.00 F	*- F
16	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)0.000.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >