

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG20014010/AEA3Q2

Date:

31/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900045236

Claimant Vehicle No : SKR9428R**Insured Vehicle No :**

SMJ2140J

Date of Loss: 14/12/2020

Nature of Claim:

TP

Claim No:

3910518695SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKR9428R**

Make & Model: AUDI A3, 1.4 TFSI AMBIENTE MY 15 (A)

Engine No: CZC230387

Reg. Date: 18/03/2015 (Man. Year: 2014)

Chassis No:

WAUZZZ8V7F1088403

Colour: Brown

Odometer:

92493 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,185.00	2,128.16	1,056.84	33.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,522.00	900.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,607.00	3,650.16	1,956.84	34.90
+ GST 7.00/7.00% (S\$)	392.49	255.51	136.98	34.90

Nett Amount (S\$)	5,999.49	3,905.67	2,093.82	34.90
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,207.67		

INSPECTION

Date of Assignment: 18/12/2020

Date Inspected: 18/12/2020

Estimated Period of Repair: 3.0 days

Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR -RH	Dented	2,494.00 FS	*1,995.20 FS
2	1		*REAR DOOR OUTER SEAL -RH	Necessary	159.00 FS	*127.20 FS
3	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
5	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	127.00 FS	*- FS
6	1		*REAR DOOR CATCH	Not Necessary	93.00 FS	*- FS
7	1		*SUNDRIES	Necessary	200.00 FS	*5.76 FS
					Total Parts (S\$)	3,185.00
						2,128.16

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	280.00	280.00
2	TO DISMANTLE AND RENEW RHS REAR DOOR .RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY RHS REAR DOOR	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,422.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >