5/17/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/III20014011/PA3Q2

Date:

17/05/2021

REFERENCE

Date of Loss:

Handling Insurer: India International Insurance Pte Ltd Policy No:

MCOM0015 SHA4011S

Claimant Vehicle No:

GBD1879E 25/11/2020

Insured Vehicle No: Nature of Claim:

ΤP

Claim No:

MCT20110417

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD1879E**

Make & Model: NISSAN NV200, 1.5 ABS AIRBAG 2WD 6DR EURO 5 (M) Engine No: K9KC400D053665

21/07/2014 (Man. Year: 2014) Reg. Date:

Chassis No: Odometer:

VSKYBAM20Z0085086

164532 km

Colour: Grev **Engine Capacity:** 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Handbrake (Serviceable):

Engine Modification:

Yes No

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

175/70 R14

Yes

Rear Tyre Size: Rear Left Side:

175/70 R14

Front Left Side: Front Right Side: Falken 6 mm Falken 6 mm

Rear Right Side:

Falken 6 mm Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,292.90	592.32	2,700.58	82.01
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,960.00	1,140.00	1,820.00	61.49
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,252.90	1,732.32	4,520.58	72.30
	Approved Total (Overridden) (S\$)		1,350.00		

Nett Amount (S\$) 6,252.90 1,350.00 4,902.90 78.41

Global Sum Settlement (S\$) 0.00

INSPECTION

Date of Assignment: 16/12/2020

C L Auto Pte Ltd (HQ)

Date Inspected: 22/12/2020 Inspected At: 48 Toh Guan Road East

48 Toh Guan Road East, #02-125 Enterprise Hub

Singapore 608586

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 May 2021)

NISSAN NV200 1.5 ABS AIRBAG 2WD 6DR EURO 5 (M) (Model not available in database) Parts: N/A

Labour: Repairer's (Price-denominated Standard List)

(Unsubmitted, no print-code for GBD1879E) **Print Code:**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR RH TAILLAMP ASSY	Not Necessary	297.00 FN	*- FN
2	1	*REAR LH TAIL LAMP SEAL	Not Necessary	432.00 FN	*- FN
3	1	*REAR LH FENDER ASSY	Repair	1,854.30 FN	*- FN
4	1	*REAR BUMPER	Scratched	624.80 FN	*624.80 FN
5	1	*REAR BUMPER BEAM	Not Necessary	120.00 FN	*- FN
6	1	*REAR BUMPER RETAINER	Not Necessary	58.00 FN	*- FN
7	1	*REAR LOWER PANEL	Not Necessary	217.12 FN	*- FN
8	1	*SET REAR BUMPER RETAINER CLIP	Necessary	50.00 FS	*30.00 FS
F=Fr	anchise part. S=SpcNet	t. N=NettItemDisc.			
			Sub Total (S\$)	3,653.22	654.80
			- Nett Item Discount on N Items 10.00/10.00% (S\$)	360.32	62.48
			Total Parts (S\$)	3,292.90	592.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>bur Items</u>			
1	TO UNDERCOATING REAR LH FENDER ASSY & BUMPER	New	280.00	40.00
2	TO CUT & WELDING REAR LH FENDER, LOWER PANEL , TAIL LAMP PANEL , REAR BUMPER BEAM & REAR TAIL LAMP ASSY AND BACK LH DOOR	New	1,400.00	400.00
3	TO PUTTY & RESPRAY PAINT REAR FENDER & TAIL LAMP & LOWER PANEL & POLISH	New	800.00	400.00
4	REAR LH FENDER COMPANY LOGO }	New	240.00	300.00
5	REAR RH FENDER COMPANY TELEPHONE NUMBER & EMAIL }	New	240.00	0.00
	Gross Labou	ur Cost (S\$)	2,960.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >