8/13/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG20014016/T1EA3Q2

Date:

13/08/2021

REFERENCE

Date of Loss:

Reg. Date:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Nature of Claim:

1800112649 SME3156J

Claimant Vehicle No:

SHB3588X 15/12/2020 Insured Vehicle No:

ΤP

Claim No:

4183877831SG

KMHC851CVLU178576

G4LEKU362999

148723 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB3588X

Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)

24/09/2019 (Man. Year: 2019)

West Lake 6 mm

Colour: Yellow

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Yes

Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: Rear Left Side:

195/65 R15 West Lake 6 mm

Front Left Side: Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,945.76	3,072.00	2,873.76	48.33
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,260.00	650.00	610.00	48.41
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	7,205.76	3,722.00	3,483.76	48.35
	+ GST 7.00/7.00% (S\$)	504.40	260.54	243.86	48.35

Nett Amount (S\$)	7,710.16	3,982.54	3,727.62	48.35
+ Loss of Use	e (2.5 x S\$50.00/day) (S\$)	125.00		
+ Car Rental	(2.5 x S\$125.19/day) (S\$)	312.98		
	+ Doc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	4,422.52		
Glo	bal Sum Settlement (S\$)	4,420.00		

INSPECTION

Date of Assignment: 16/12/2020

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: Inspected At: 16/12/2020

59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER COVER	Repair	418.30 FL	*- FL
2	1	*FRONT BUMPER BRACKET RH	Not Necessary	35.00 FL	*- FL
3	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	1,075.10 FL	*-FL
4	1	*FRONT BUMPER CENTRE MOULDING	Cut	368.50 FL	*368.50 FL
5	1	*FRONT RADIATOR GRILLE	Cut	1,409.10 FL	*1,409.10 FL
6	1	*FRONT BUMPER LOWER STIFFNER	Not Necessary	285.10 FL	*- FL
7	1	*HEAD LAMP SUPPORT PANEL	Not Necessary	949.30 FL	*- FL
8	1	*HEAD LAMP RH	Cut	1,993.65 FL	*1,993.65 FL
9	1	*FRONT DAY LIGHT RH	Not Necessary	642.50 FL	*- FL
10	1	*BUMPER GRILLE RH	Not Necessary	186.90 FL	*- FL
11	1	*FRONT NUMBER PLATE W/HOLDER	Cracked	55.00 FS	*55.00 FS
F=Fr	anchise part. S=SpcNett	. L=ListItemDisc.			
			Sub Total (S\$)	7,418.45	3,826.25
			- List Item Discount on L Items 20.00/20.00% (S\$)	1,472.69	754.25
			Total Parts (S\$)	5,945.76	3,072.00
		Report	was unsubmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particul	lars	Lab.Type	Repairer's	Amount
Labour Items	2			
1 PANEL	BEATING	New	640.00	320.00
2 SPRAY	PAINTING CHARGE	New	500.00	300.00
3 WIRING)	New	60.00	30.00
4 TUFF K	OTE	New	60.00	0.00
		Gross Labour Cost (S\$)	1,260.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >