Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014017/T1BA3Q2

Date: 18/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100502207

Claimant
Vehicle No: SHD1461E

Insured Vehicle No: SLL5073B

Date of Loss: 16/12/2020 Nature of Claim: TP Claim No: 9403343840SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD1461E

 Make & Model:
 HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)
 Engine No:
 D4FBGZ127648

 Reg. Date:
 26/07/2017 (Man. Year: 2016)
 Chassis No:
 TMAD281UVHJ129437

Colour: Silver Odometer: 496437 km

Engine Capacity: 1582 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
Front Right Side: Maxxis 6 mm
Maxxis 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|--------------------|------------|------------|--------|
| Parts | 2,168.00 | 982.41 | 1,185.59 | 54.69 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,600.00 | 730.00 | 870.00 | 54.38 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 3,768.00 | 1,712.41 | 2,055.59 | 54.55 |
| Approved Total (Overridden) (S\$) | | 1,350.00 | | |
| (S\$) | 3,768.00 | 1,350.00 | 2,418.00 | 64.17 |
| + GST 7.00/7.00% (S\$) | 263.76 | 94.50 | 169.26 | 64.17 |
| Nett Amount (S\$) | 4,031.76 | 1,444.50 | 2,587.26 | 64.17 |
| + Loss of Use (3.0 x S\$ | 50.00/day) (S\$) | 150.00 | | |
| + Car Rental (3.0 x S\$ | 202.23 | | | |
| + Doc/S | earch Fee (S\$) | 2.00 | | |
| Ne | tt Liability (S\$) | 1,798.73 | | |

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 16/12/2020 Inspected At: Premier Automotive Services Pte Ltd

(HQ)

23 Changi South Ave 2, #01-02

Singapore 486443

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: MOHD TAUFIKH BIN HAMID Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | | | |
|---|--|----------|-------------------------------------|---------------------|---------------------------|-------------|--|--|--|
| 1 | 1 | | *TAILGATE LOWER GARNISH | Repair | 362.61 FL | *- FL | | | |
| 2 | 1 | | *EMBLEM CRDI | Necessary | 29.40 FL | *29.40 FL | | | |
| 3 | 1 | | *EMBLEM HYUDAI | Not Necessary | 29.40 FL | *-FL | | | |
| 4 | 1 | | *REAR BUMPER | Deformed | 811.11 FL | *811.11 FL | | | |
| 5 | 1 | | *REAR BUMPER SPONGE | Not Necessary | 79.20 FL | *-FL | | | |
| 6 | 1 | | *REAR BUMPER REINFORCEMENT | Not Necessary | 815.64 FL | *- FL | | | |
| 7 | 1 | | *REAR BUMPER REINFORCEMENT CENTRE | Not Necessary | 79.20 FL | *- FL | | | |
| 8 | 2 | | *REAR BUMPER N/S & O/S SIDE BRACKET | Not Necessary | 104.40 FL | *- FL | | | |
| 9 | 2 | | *REAR BUMPER N/S & O/S REFLECTOR | Not Necessary | 107.50 FL | *-FL | | | |
| 10 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 48.00 FS | S *30.00 FS | | | |
| 11 | 1 | | *SET REVERSE SENSOR | Not Working | 280.00 FS | *200.00 FS | | | |
| 12 | 1 | | *SET TAILGATE STICKERS | Necessary | 100.00 FS | *60.00 FS | | | |
| 13 | 1 | | *SET TAILGATE LOWER GARNISH CLIPS | Not Necessary 38.00 | | *-FS | | | |
| 14 | 1 | | *REAR BUMPER PROTECTOR | Not Necessary | 80.00 FS | *-FS | | | |
| 15 | 1 | | *SUNDRY | Necessary | 50.00 FS | *20.00 FS | | | |
| F=Fra | F=Franchise part. S=SpcNett. L=ListItemDisc. | | | | | | | | |
| | | | | Sub Total (S\$) | 3,014.46 846.46 | 1,150.51 | | | |
| | - List Item Discount on L Items 35.00/20.00% (S\$) | | | | | 168.10 | | | |
| | | | | Total Parts (S\$) | 2,168.00 | 982.41 | | | |
| Report was unsubmitted during this print-out. | | | | | | | | | |

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount | | | | |
|-----|---|--------------------|------------|--------|--|--|--|--|
| Lab | Labour Items | | | | | | | |
| 1 | TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM | New | 80.00 | 30.00 | | | | |
| 2 | TO DISMANTLE AND REFIT THE INNER COMPONENTS OF THE TAILGATE INTO NEW TAILGATE ,TEST WIPER MOTOR AND WATER ETC | New | 120.00 | 0.00 | | | | |
| 3 | TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE OF THE END PANEL ETC | ≣ New | 650.00 | 300.00 | | | | |
| 4 | TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE LOWER GARNISH ,END PANEL | New | 600.00 | 400.00 | | | | |
| 5 | TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS | New | 150.00 | 0.00 | | | | |
| | Gross Labou | 1,600.00 | 730.00 | | | | | |
| | Report was unsubmitted durin | ng this print-out. | | | | | | |

< END OF ESTIMATES >