

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014021/QGS3Q2
Date: 28/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700032821
Claimant Vehicle No :	SLE233B	Insured Vehicle No :	SLQ9662Z
Date of Loss:	14/12/2020	Nature of Claim:	TP
		Claim No:	1267630528SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE233B	Engine No:	L15B31021310
Make & Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Chassis No:	JHMGK5850GX203105
Reg. Date:	15/07/2016 (Man. Year: 2016)	Odometer:	95178 km
Colour:	Purple		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	650.00	150.00	18.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	800.00	650.00	150.00	18.75
+ GST 7.00/7.00% (S\$)	56.00	45.50	10.50	18.75

Nett Amount (S\$)	856.00	695.50	160.50	18.75
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		882.99		

INSPECTION

Date of Assignment: 17/12/2020

Date Inspected: 21/12/2020

Estimated Period of Repair: 2.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT REAR BOOT TWO PORTIONS	New	250.00	250.00
2	TO RESPRAY AFFECTED AREAS	New	350.00	350.00
3	TO CHECK ON EFFECTED AREA WIRING SYSTEM	New	80.00	20.00
4	TO TEST AND REFIT REVERSE SENSOR SY	New	120.00	30.00
Gross Labour Cost (S\$)			800.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >