

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014024/UTF3Q2

Date: 11/01/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00035802002
Claimant Vehicle No :	SLE6142R	Insured Vehicle No :	SGB890D
Date of Loss:	13/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D204885/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE6142R	Engine No:	G4FGGH623418
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFZ411MH5636670
Reg. Date:	28/07/2016 (Man. Year: 2016)	Odometer:	134668 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45ZR17	Rear Tyre Size:	215/45ZR17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,977.64	4,866.30	8,111.34	62.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	1,760.00	2,370.00	57.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	17,107.64	6,626.30	10,481.34	61.27
Approved Total (Overridden) (\$)		5,300.00		
Nett Amount (\$)	17,107.64	5,300.00	11,807.64	69.02

INSPECTION

Date of Assignment:	17/12/2020	
Date Inspected:	17/12/2020	Inspected At:
		Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53 Repairer: Zoom Autowerks Pte Ltd
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2021)
Parts:	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE6142R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Not Necessary	935.40 FL	*- FL
2	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	298.30 FL	*- FL
3	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
4	1		*FRONT WING MIRROR ASSY LH	Not Necessary	876.40 FL	*- FL
5	1		*FRONT DOOR LH	Badly Dented	995.70 FL	*995.70 FL
6	1		*FRONT DOOR OUTER HANDLE GARNISH LH	Cut	195.80 FL	*195.80 FL
7	1		*FRONT DOOR OUTER GLASS MOULDING LH	Not Necessary	255.60 FL	*- FL
8	1		*FRONT DOOR TOP HINGE LH	Not Necessary	128.60 FL	*- FL
9	1		*FRONT DOOR LOWER HINGE LH	Not Necessary	132.50 FL	*- FL
10	1		*FRONT DOOR INNER LOCK LH	Shorted	496.50 FL	*496.50 FL
11	1		*FRONT DOOR WEATHER STRIP LH	Necessary	386.70 FL	*145.00 FL
12	1		*FRONT DOOR INNER TRIMBOARD LH	Deformed/Torn	786.40 FL	*522.30 FL
13	1		*SET FRONT DOOR INNER TRIMBOARD CLIPS LH	Necessary	60.00 FL	*60.00 FL
14	1		*FRONT DOOR POWER WINDOW MOTOR/LINKAGE ASSY LH	Jammed	755.20 FL	*495.30 FL
15	1		*REAR DOOR LH	Dented/Bent	920.70 FL	*920.70 FL
16	1		*REAR DOOR OUTER GLASS MOULDING LH	Not Necessary	198.70 FL	*- FL
17	1		*REAR DOOR TOP HINGE LH	Not Necessary	128.60 FL	*- FL
18	1		*REAR DOOR LOWER HINGE LH	Not Necessary	132.50 FL	*- FL
19	1		*REAR DOOR INNER LOCK LH	Not Necessary	496.50 FL	*- FL
20	1		*REAR DOOR WEATHER STRIP LH	Necessary	386.70 FL	*142.00 FL
21	1		*REAR DOOR INNER TRIMBOARD LH	Not Necessary	755.80 FL	*- FL
22	1		*SET REAR DOOR INNER TRIMBOARD CLIPS LH	Not Necessary	60.00 FL	*- FL
23	1		*REAR DOOR POWER WINDOW MOTOR/LINKAGE ASSY LH	Not Necessary	755.20 FL	*- FL
24	1		*REAR DOOR QUARTER GLASS MOULDING LH	Not Necessary	295.70 FL	*- FL
25	1		*REAR BUMPER	Cut/Torn	1,186.20 FL	*688.00 FL
26	1		*REAR FENDER INNER SHIELD LH	Not Necessary	320.00 FL	*- FL
27	1		*REAR WHEEL HUB LH	Not Necessary	395.80 FL	*- FL
28	1		*REAR WHEEL HUB BEARING LH	Damaged	245.70 FL	*245.70 FL
29	1		*REAR SHOCK ABSORBER LH	Not Necessary	398.40 FL	*- FL
30	1		*REAR SPORT RIM LH	Cut	1,242.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,281.60	5,357.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,303.96	490.70
Total Parts (\$\$)	12,977.64	4,866.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,200.00	600.00
2	TO PUTTY,SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS	New	1,400.00	800.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL FRONT DOOR COMPONENTS	New	150.00	60.00
5	TO REMOVE & INSTALL REAR DOOR COMPONENTS	New	150.00	60.00
6	TO REMOVE & INSTALL REAR LEFT UNDERCARRIAGE COMPONENTS	New	250.00	100.00
7	TO CONDUCT ALL WHEEL ALIGNMENT	New	280.00	60.00
8	TO DIAGNOSTIC & RESET TO SPECIFICATION	New	450.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	60.00
Gross Labour Cost (S\$)			4,130.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >