

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20014025/UTF3Q2

**Date:** 05/01/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00059412001
<b>Claimant Vehicle No :</b>	SLD9654R	<b>Insured Vehicle No :</b>	SKB5096A
Date of Loss:	10/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D204852/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLD9654R</b>		
Make & Model:	TOYOTA SIENTA, 1.5 G CVT ABS D/AIRBAG 2WD 5DR (A)	Engine No:	2NR8545182
Reg. Date:	01/07/2016 (Man. Year: 2015)	Chassis No:	NSP1707010971
Colour:	Silver	Odometer:	64078 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	HIFLY 6 mm	Rear Left Side:	HIFLY 6 mm
Front Right Side:	HIFLY 6 mm	Rear Right Side:	HIFLY 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,707.57	3,724.57	7,983.00	68.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	2,070.00	2,730.00	56.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>16,507.57</b>	<b>5,794.57</b>	<b>10,713.00</b>	<b>64.90</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,600.00</b>		
<b>Nett Amount (\$\$)</b>	<b>16,507.57</b>	<b>4,600.00</b>	<b>11,907.57</b>	<b>72.13</b>

### INSPECTION

Date of Assignment:	17/12/2020	
Date Inspected:	17/12/2020 Inspected At:	1st Auto Pro Pte Ltd - 8 Kaki Bukit (HQ)
		8 Kaki Bukit Avenue 4, #01-51/52
		PREMIER @ KAKI BUKIT
		Singapore 415875
Estimated Period of Repair:	5.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2021)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA 1.5 G CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLD9654R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	1,380.50 FL	*645.10 FL
2	1		*REAR BUMPER CENTRE GARNISH	Cut	498.60 FL	*245.10 FL
3	2		*REAR BUMPER LOWER BRACKET LH/RH	No such part	231.60 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	520.00 FL	*- FL
5	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	560.00 FL	*- FL
6	1		*REAR END PANEL	Badly Dented	922.80 FL	*522.10 FL
7	1		*REAR END PANEL INNER GARNISH	Twisted	312.60 FL	*165.80 FL
8	1		*REAR PANEL LOCK CATCH LOWER	Not Necessary	152.20 FL	*- FL
9	1		*REAR BOOT	Badly Dented	2,065.00 FL	*1,281.20 FL
10	2		*REAR BOOT HINGE LH/RH	Not Necessary	436.00 FL	*- FL
11	1		*REAR BOOT COVER RUBBER MOULDING	Necessary	180.00 FL	*145.80 FL
12	1		*REAR BOOT LOCK UPPER	Dented/Jammed	335.60 FL	*335.60 FL
13	1		*REAR BOOT OUTER GARNISH CENTRE	Not Necessary	289.60 FL	*- FL
14	2		*REAR BOOT LAMP LH/RH	Not Necessary	1,045.80 FL	*- FL
15	1		*REAR BOOT INNER TRIM	Deformed/Torn	481.00 FL	*241.10 FL
16	1		*REAR BOOT LOGO	Necessary	180.00 FL	*58.10 FL
17	1		*REAR FENDER INNER TRIM BOARD O/S	Twisted	486.20 FL	*486.20 FL
18	1		*REAR BOOT STOPPER	Not Necessary	194.40 FL	*- FL
19	2		*REAR TAIL LAMP LH/RH	Not Necessary	1,451.80 FL	*- FL
20	2		*REAR TAIL LAMP SIDE PANEL LH/RH	Repair	678.40 FL	*- FL
21	2		*REAR FENDER INNER SHIELD LH/RH	Not Necessary	539.00 FL	*- FL
22	1		*SPARE WHEEL CARRIER	Not Necessary	560.00 FL	*- FL
23	1		*REAR EXHAUST SILENCER	Not Necessary	925.00 FL	*- FL
24	1		*REAR EXHAUST MOUNTING	Not Necessary	184.00 FL	*- FL
25	1		*REAR NUMBER PLATE WITH GARNISH	Scratched	100.00 FS	*40.00 FS
26	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
27	1		*SET REAR REVERSE CAMERA	Shorted	300.00 FS	*300.00 FS
28	1		*SET REAR BUMPER SENSOR	Shorted	200.00 FS	*200.00 FS
29	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>15,360.10</b>	<b>4,756.10</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	3,652.53	1,031.53
<b>Total Parts (\$\$)</b>	<b>11,707.57</b>	<b>3,724.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE,REFIT AND TRANSFER REAR BOOT COMPONENT	New	250.00	60.00
2	TO REMOVE AND REFIT ELECTRICAL WIRING,REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING-REAR	New	250.00	20.00
3	TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR	New	250.00	80.00
4	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	50.00
5	TO REMOVE AND REFIT,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTING	New	350.00	0.00
6	TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	New	100.00	60.00
7	TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	New	2,000.00	1,000.00
8	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	New	1,500.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,800.00</b>	<b>2,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >